2006 Hitachi ZX200 Hydraulic Excavator

| Donio informatica | | | |
|--|--|--|---------------------------------|
| Basic information | 7Y200 | Sorial No. | 117160 |
| Model Product estagery | ZX200 | Serial No. Manufacturer | 117162 Hitachi |
| Product category Year of manufacture | Hydraulic Excavator | | |
| | 2006 | Working hours | 7400 hours |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Rental | Cabin / Canopy | Cabin |
| Front Attachment | Standard | Type of Shoe | Grouser |
| Width of Track Shoe | 600 | Bucket Attachment | Standard |
| Other | EPA, Air Conditioner, Multi Lever, Arm Crane | | |
| Appearance | | | |
| Engine Cover | Good Condition | Side Covers | Rusted / Corroded |
| Under Covers | Rusted / Corroded | Counter Weight | Scratched |
| Main Frame | Rusted / Corroded | D Frame | Rusted / Corroded |
| Track Frame | Rusted / Corroded | Cabin | Rusted / Corroded |
| Door | Good Condition | | |
| Interior | | | |
| Cabin Interior | Good Condition | Seat | Good Condition |
| Console | Good Condition | Air Conditioner | Good |
| | 2000 Condition | , ai Conditionol | |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Moderate / within Service Limit |
| Traveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | |
| Front & Pins | | | |
| Boom | Normal | Arm | Reinforcement |
| Wear: Boom Foot Pin | Moderate / within Service Limit | Wear: Boom / Arm Joint Pin | Slight |
| Wear: Arm Tip Pin | Heavy | Wear: Other Pins | Heavy |
| Wear / Deformation: Bucket | Deformation: Heavy | | |
| Undercarriage / Chassis / | Tires | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Slight |
| Wear: Track Link Stretching (Left) | Slight | Wear: Track Link Tread (Right) | Slight |
| Wear: Track Link Tread (Left) | Slight | Wear: Track Link Pins & Bushings (Right) | Slight |
| Wear: Track Link Pins & Bushings (Left) | Slight | Wear: Track Shoe / Rubber Shoe | Slight |
| Bent / Broken / Missing: Track Shoe | No | Wear: Upper Rollers | Moderate / within Service Limit |
| Wear: Lower Rollers | Moderate / within Service Limit | Oil Leak: Rollers | None |
| Broken / Missing: Rollers | None | Wear: Front Idler (Right) | Slight |
| Near: Front Idler (Left) | Slight | Wear: Sprocket (Right) | Slight |
| Wear: Sprocket (Left) | Slight | Oil Leak: Travel Device | None |
| Oil Leak: Travel Pipes | None | | |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder (Right) | None |
| Oil Leak: Boom Cylinder (Left) | None | Oil Leak: Arm Cylinder (Right) | None |
| | | | |

| Oil Leak: Bucket Cylinder (Right) | None | Oil Leak: Engine | Slight Film |
|-----------------------------------|-------------|---------------------------------|---------------------------------|
| Oil Leak: Oil Cooler | None | Leak: Radiator | None |
| Leak: Cooling Pipes | None | Oil Leak: Fuel System | None |
| Oil Leak: Control Valve | None | Oil Leak: Low Pressure Pipes | None |
| Oil Leak: High Pressure Pipes | None | Oil Leak: Pilot Pipes | Slight Film |
| Oil Leak: Pilot Valve | Slight Film | Oil Leak: Center Joint | None |
| Oil Leak: Swing Device | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |