1998 Komatsu PC35R-8 Mini Excavator

Basic information			
Model	PC35R-8	Serial No.	37261
Product category	Mini Excavator	Manufacturer	Komatsu
Year of manufacture	1998	Working hours	7341 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canony
Front Attachment	Standard	Type of Shoe	Canopy Rubber
Width of Track Shoe	300	Bucket Attachment	Standard
Water of Track Office	300	Ducket Attachment	Standard
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Jnder Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Torn	Console	Faded
Operation			
Operation	Normal	Exhaust Cas Calar	Normal
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Deformed / Dent
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Near: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tires		
Wear: Track Link		Wear: Track Link	
Stretching (Right)	Slight	Stretching (Left)	Slight
Wear: Track Link Tread	Madarata / within Camina Limit	Wear: Track Link Tread	Madarata / within Carriag Limit
(Right)	Moderate / within Service Limit	(Left)	Moderate / within Service Limit
Wear: Track Link Pins &	Moderate / within Service Limit	Wear: Track Link Pins &	Moderate / within Service Limit
Bushings (Right)	20.100	Bushings (Left)	San
Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	Broken / Crack: Rubber	Some Tears
Snoe Broken / Crack: Rubber		Shoe (Right)	
Shoe (Left)	Some Tears	Missing: Rubber Shoe Core	No
Near: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Excessive / Required to replace
Dil Leak: Rollers	None	Broken / Missing: Rollers	None
Near: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Near: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage	NI	O'll sal D	Olimba Film
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	Slight Film
Dil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Dil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
_eak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	Slight Film	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes Oil Leak: Pump Device	None
Oil Leak: Pilot Valve	None		Slight Film

Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		