

# 1999 Komatsu PC128US-2 Hydraulic Excavator

| Basic information                       |                                 |                                          |                                 |
|-----------------------------------------|---------------------------------|------------------------------------------|---------------------------------|
| Model                                   | PC128US-2                       | Serial No.                               | 5363                            |
| Product category                        | Hydraulic Excavator             | Manufacturer                             | Komatsu                         |
| Year of manufacture                     | 1999                            | Working hours                            | 5953 hours                      |
| Engine No.                              |                                 |                                          |                                 |
| Detail Information                      |                                 |                                          |                                 |
| Job Status                              | Civil Engineering               | Cabin / Canopy                           | Cabin                           |
| Front Attachment                        | Standard                        | Type of Shoe                             | Grouser with Pad                |
| Width of Track Shoe                     | 500                             | Bucket Attachment                        | Standard                        |
| Other                                   | Arm Crane                       |                                          |                                 |
| Appearance                              |                                 |                                          |                                 |
| Engine Cover                            | Rusted / Corroded               | Side Covers                              | Rusted / Corroded               |
| Under Covers                            | Rusted / Corroded               | Counter Weight                           | Scratched                       |
| Main Frame                              | Rusted / Corroded               | D Frame                                  | Rusted / Corroded               |
| Track Frame                             | Rusted / Corroded               | Cabin                                    | Rusted / Corroded               |
| Door                                    | Latch Malfunction               |                                          |                                 |
| Interior                                |                                 |                                          |                                 |
| Cabin Interior                          | Torn                            | Seat                                     | Torn                            |
| Console                                 | Malfunction                     | Air Conditioner                          | Malfunction                     |
| Operation                               |                                 |                                          |                                 |
| Engine                                  | Normal                          | Exhaust Gas Color                        | Normal                          |
| Swing                                   | Normal                          | Wear: Swing Bearing                      | Slight                          |
| Traveling                               | Normal                          | Front Attachment                         | Normal                          |
| Pump Device                             | Normal                          |                                          |                                 |
| Front & Pins                            |                                 |                                          |                                 |
| Boom                                    | Normal                          | Arm                                      | Reinforcement                   |
| Wear: Boom Foot Pin                     | Moderate / within Service Limit | Wear: Boom / Arm Joint Pin               | Moderate / within Service Limit |
| Wear: Arm Tip Pin                       | Moderate / within Service Limit | Wear: Other Pins                         | Moderate / within Service Limit |
| Wear / Deformation: Bucket              | Deformation: Moderate           |                                          |                                 |
| Undercarriage / Chassis / Tires         |                                 |                                          |                                 |
| Seize: Track Links                      | No                              | Wear: Track Link Stretching (Right)      | Slight                          |
| Wear: Track Link Stretching (Left)      | Slight                          | Wear: Track Link Tread (Right)           | Slight                          |
| Wear: Track Link Tread (Left)           | Slight                          | Wear: Track Link Pins & Bushings (Right) | Slight                          |
| Wear: Track Link Pins & Bushings (Left) | Slight                          | Wear: Track Shoe / Rubber Shoe           | Slight                          |
| Bent / Broken / Missing: Track Shoe     | No                              | Wear: Rubber Pad                         | Excessive / Required to replace |
| Broken / Missing: Rubber Pad            | Broken / Missing (Left)         | Missing: Rubber Pad                      | more than 10 Pieces             |
| Wear: Upper Rollers                     | Slight                          | Wear: Lower Rollers                      | Slight                          |
| Oil Leak: Rollers                       | None                            | Broken / Missing: Rollers                | 1 - 4 Pieces                    |
| Wear: Front Idler (Right)               | Slight                          | Wear: Front Idler (Left)                 | Slight                          |
| Wear: Sprocket (Right)                  | Slight                          | Wear: Sprocket (Left)                    | Slight                          |
| Oil Leak: Travel Device                 | None                            | Oil Leak: Travel Pipes                   | None                            |
| Oil / Water / Air Leakage               |                                 |                                          |                                 |
| Oil Leak: Front Pipes                   | None                            | Oil Leak: Boom Cylinder (Right)          | None                            |

|                                   |             |                                |                                 |
|-----------------------------------|-------------|--------------------------------|---------------------------------|
| Oil Leak: Boom Cylinder (Left)    | None        | Oil Leak: Arm Cylinder (Right) | None                            |
| Oil Leak: Bucket Cylinder (Right) | None        | Oil Leak: Engine               | Slight Film                     |
| Oil Leak: Oil Cooler              | None        | Leak: Radiator                 | None                            |
| Leak: Cooling Pipes               | None        | Oil Leak: Fuel System          | None                            |
| Oil Leak: Control Valve           | Slight Film | Oil Leak: Low Pressure Pipes   | Slight Film                     |
| Oil Leak: High Pressure Pipes     | Slight Film | Oil Leak: Pilot Pipes          | None                            |
| Oil Leak: Pilot Valve             | None        | Oil Leak: Center Joint         | Slight Film                     |
| Oil Leak: Swing Device            | Slight Film | Oil Leak: Pump Device          | None                            |
| Overall Rating                    |             |                                |                                 |
| Appearance Evaluation             | Poor        | Rust / Corrosion               | Moderate / within Service Limit |
| Overall Rating                    | Usable      |                                |                                 |