1997 Komatsu JW215 Roller

| Basic information | | | |
|---|---------------------------------|-------------------------------------|---------------------------------|
| Model | JW215 | Serial No. | JW2151-10097 |
| Product category | Roller | Manufacturer | Komatsu |
| Year of manufacture | 1997 | Working hours | 3005 hours |
| Engine No. | | | |
| Detail Information | | | |
| Power Transmission System | HST | Drive System | Rear Drive |
| Appearance | | | |
| Main Frame | Rusted / Corroded | Canopy | Rusted / Corroded |
| Interior | | | |
| Seat | Torn | Console | Faded, Malfunction |
| Operation | | | |
| Wear / Scratches: Tire (Front Wheel) | Moderate / within Service Limit | Wear / Scratches: Tire (Rear Wheel) | Moderate / within Service Limit |
| Oil Leak: Travel Device | No | Oil Leak: Travel Pipes | No |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Steering Cylinder | No | Oil Leak: Engine | Slight Film |
| Pump Device | Slight Film | Transmission / Torque Converter | No |
| Engine | Normal | Exhaust Gas Color | Normal |
| Traveling | Normal | Transmission / Torque Converter | Normal |
| Break | Normal | Side Break | Normal |
| Undercarriage / Chassis / | Tires | | |
| Oil Leak: Oil Cooler | No | Leak: Radiator | No |
| Leak: Cooling Pipes | No | Oil Leak: Fuel System | Slight Film |
| Oil Leak: Control Valve | No | Oil Leak: Low Pressure Pipes | No |
| Oil Leak: High Pressure Pipes | No | | |
| Overall Rating | | | |
| Appearance Evaluation | Poor | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Usable | | |