## 2006 Hitachi ZX135US Hydraulic Excavator

| Desir inf                                  |  |  |                                 |
|--|--|--|---------------------------------|
| Basic information                          | 7/405110                                     | OINI-                                    | 70000                           |
| Model                                      | ZX135US                                      | Serial No.                               | 72832                           |
| Product category                           | Hydraulic Excavator                          | Manufacturer                             | Hitachi                         |
| Year of manufacture                        | 2006   | Working hours                            | 7164 hours                      |
| Engine No.                                 |  |  |                                 |
| Detail Information                         |  |  |                                 |
| Job Status                                 | Rental                                       | Cabin / Canopy                           | Cabin                           |
| Front Attachment                           | Standard                                     | Type of Shoe                             | Grouser                         |
| Width of Track Shoe                        | 500  | Bucket Attachment                        | Standard                        |
| Other                                      | Piping, EPA, Air Conditioner, Multi<br>Lever |  |                                 |
| Appearance                                 |  |  |                                 |
| Engine Cover                               | Rusted / Corroded                            | Side Covers                              | Rusted / Corroded               |
| Under Covers                               | Rusted / Corroded                            | Counter Weight                           | Scratched                       |
| Main Frame                                 | Rusted / Corroded                            | D Frame                                  | Rusted / Corroded               |
| Track Frame                                | Rusted / Corroded                            | Cabin                                    | Rusted / Corroded               |
| Door                                       | Good Condition                               |  |                                 |
| Interior                                   |  |  |                                 |
| Cabin Interior                             | Good Condition                               | Seat                                     | Torn                            |
| Console                                    | Good Condition                               | Air Conditioner                          | Good                            |
|  |  |  |                                 |
| Operation                                  | NI   | Full accet One Onlan                     | NI                              |
| Engine                                     | Normal                                       | Exhaust Gas Color                        | Normal                          |
| Swing                                      | Normal                                       | Wear: Swing Bearing                      | Moderate / within Service Limit |
| Traveling                                  | Normal                                       | Front Attachment                         | Normal                          |
| Pump Device                                | Normal                                       |  |                                 |
| Front & Pins                               |  |  |                                 |
| Boom                                       | Normal                                       | Arm                                      | Reinforcement                   |
| Wear: Boom Foot Pin                        | Heavy  |  | Moderate / within Service Limit |
| Wear: Arm Tip Pin                          | Heavy  | Wear: Other Pins                         | Heavy                           |
| Wear / Deformation: Bucket                 | Deformation: Moderate                        |  |                                 |
| Undercarriage / Chassis /                  | Tires  |  |                                 |
| Seize: Track Links                         | No   | Wear: Track Link<br>Stretching (Right)   | Slight                          |
| Wear: Track Link<br>Stretching (Left)      | Slight                                       | Wear: Track Link Tread (Right)           | Slight                          |
| Wear: Track Link Tread<br>(Left)           | Slight                                       | Wear: Track Link Pins & Bushings (Right) | Slight                          |
| Wear: Track Link Pins &<br>Bushings (Left) | Slight                                       | Wear: Track Shoe / Rubber Shoe           | Slight                          |
| Bent / Broken / Missing:<br>Track Shoe     | No   | Wear: Upper Rollers                      | Slight                          |
| Wear: Lower Rollers                        | Slight                                       | Oil Leak: Rollers                        | None                            |
| Broken / Missing: Rollers                  | None   | Wear: Front Idler (Right)                | Slight                          |
| Wear: Front Idler (Left)                   | Slight                                       | Wear: Sprocket (Right)                   | Moderate / within Service Limit |
| Wear: Sprocket (Left)                      | Moderate / within Service Limit              | Oil Leak: Travel Device                  | None                            |
| Oil Leak: Travel Pipes                     | None   |  |                                 |
| Oil / Water / Air Leakage                  |  |  |                                 |
| Oil Leak: Front Pipes                      | None   | Oil Leak: Boom Cylinder (Right)          | None                            |
| Oil Leak: Boom Cylinder<br>(Left)          | None   | Oil Leak: Arm Cylinder<br>(Right)        | None                            |
|  |  |  |                                 |

| Oil Leak: Bucket Cylinder (Right) | None | Oil Leak: Engine                | Slight Film                     |
|-----------------------------------|------|---------------------------------|---------------------------------|
| Oil Leak: Oil Cooler              | None | Leak: Radiator                  | None                            |
| Leak: Cooling Pipes               | None | Oil Leak: Fuel System           | None                            |
| Oil Leak: Control Valve           | None | Oil Leak: Low Pressure<br>Pipes | None                            |
| Oil Leak: High Pressure<br>Pipes  | None | Oil Leak: Pilot Pipes           | None                            |
| Oil Leak: Pilot Valve             | None | Oil Leak: Center Joint          | None                            |
| Oil Leak: Swing Device            | None | Oil Leak: Pump Device           | Slight Film                     |
| Overall Rating                    |      |                                 |                                 |
| Appearance Evaluation             | Poor | Rust / Corrosion                | Moderate / within Service Limit |
| Overall Rating                    | Fair |                                 |                                 |