1993 Yanmar B37-2 Mini Excavator

Basic information			
Model	B37-2	Serial No.	21480B
Product category	Mini Excavator	Manufacturer	Yanmar
Year of manufacture	1993	Working hours	4809 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canany	Canany
Front Attachment	Civil Engineering Standard	Cabin / Canopy Type of Shoe	Canopy Rubber
Width of Track Shoe	370	Bucket Attachment	Standard
Width of Track Shoe	370	Ducket Attacriment	Standard
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Required to Repair / Replace	Console	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Deformed / Dent
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	.	Wear / Deformation: Blade	Wear: Moderate / within Service Limi
Undersorriege / Chassis /	Timo		
Undercarriage / Chassis /	Tiles		
Wear: Track Link Stretching (Right)	Slight	Wear: Track Link Stretching (Left)	Slight
Wear: Track Link Tread		Wear: Track Link Tread	
(Right)	Moderate / within Service Limit	(Left)	Moderate / within Service Limit
Wear: Track Link Pins &	Madayata / within Camina Limit	Wear: Track Link Pins &	Madagata / within Camina Limit
Bushings (Right)	Moderate / within Service Limit	Bushings (Left)	Moderate / within Service Limit
Wear: Track Shoe / Rubber	Moderate / within Service Limit	Broken / Crack: Rubber	No
Shoe	Widderday William Colvido Limit	Shoe (Right)	
Broken / Crack: Rubber	No	Missing: Rubber Shoe Core	No
Shoe (Left) Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	1 - 4 Pieces	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Excessive / Required to replace	Wear: Front Idler (Left)	Excessive / Required to replace
Wear: Sprocket (Right) Oil Leak: Travel Device	Slight	Wear: Sprocket (Left)	Slight
Oil Leak. Havei Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
	Slight Film	Oil Leak: Upper Structure	None
Oil Leak: Fuel System	Chight thin the		
Oil Leak: Fuel System Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None

Overall Rating

Appearance Evaluation Poor Rust / Corrosion Moderate / within Service Limit

Overall Rating Usable