2006 Komatsu PC78US-6N0 Hydraulic Excavator

Basic information			
Model	PC78US-6N0	Serial No.	10023
Product category	Hydraulic Excavator	Manufacturer	Komatsu
Year of manufacture	2006	Working hours	6958 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Cabin
	Standard	Type of Shoe	Grouser
	450	Bucket Attachment	Standard
Other	Piping, EPA, Air Conditioner, Multi Lever, Quick Hitch		
Appearance			
Engine Cover	Good Condition	Side Covers	Rusted / Corroded
	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
	Rusted / Corroded	Cabin	Rusted / Corroded
	Good Condition		
Interior			
	Good Condition	Seat	Burned by Cigarette
	Good Condition	Air Conditioner	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Repair Mark	Arm	Reinforcement
Wear: Boom Foot Pin	Heavy	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	1 - 4 Pieces	Wear: Upper Rollers	Slight
Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
		Moore Front Idlar (Dight)	Slight
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	
Broken / Missing: Rollers Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)			
Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Slight	Wear: Sprocket (Right)	Slight
Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Slight Slight	Wear: Sprocket (Right)	Slight
Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil / Water / Air Leakage	Slight Slight	Wear: Sprocket (Right)	Slight

Oil Leak: Blade Cylinder	None	Oil Leak: Engine	Slight Film
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	Slight Film
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		