## 1997 Kubota U-10-3 Mini Excavator

Basic information			
Model	U-10-3	Serial No.	11230
Product category	Mini Excavator	Manufacturer	Kubota
Year of manufacture	1997	Working hours	3476 hours
Engine No.			
Detail Information			
	Ois di Essadas a sala s	O-hi- / O	N- CAR/OND
Job Status	Civil Engineering Standard	Cabin / Canopy	No CAB/CNP
Front Attachment  Width of Track Shoe	180	Type of Shoe	Rubber
Other		Bucket Attachment	Standard
Juliei	Extended Truck Frame		
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Jnder Covers	Rusted / Corroded	Counter Weight	Rusted / Corroded
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Interior			
Seat	Good Condition		
TT.T.:	2334 Containon		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Near: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Near / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tirae		
<del>.</del>	11165	Was Track Link	
Wear: Track Link Stretching (Right)	Slight	Wear: Track Link Stretching (Left)	Slight
Wear: Track Link Tread		Wear: Track Link Tread	
(Right)	Moderate / within Service Limit	(Left)	Moderate / within Service Limit
Wear: Track Link Pins &	Madagata / within Complete Limit	Wear: Track Link Pins &	Madagata / within Camina Limit
Bushings (Right)	Moderate / within Service Limit	Bushings (Left)	Moderate / within Service Limit
Wear: Track Shoe / Rubber	Moderate / within Service Limit	Broken / Crack: Rubber	Some Tears
Shoe	Wilder and Service Entire	Shoe (Right)	Como rodio
Broken / Crack: Rubber	Some Tears	Missing: Rubber Shoe Core	No
Shoe (Left) Vear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers		Wear: Front Idler (Right)	
Wear: Front Idler (Left)	None	Wear: Sprocket (Right)	Slight
	Slight		Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
_eak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None

Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		