

2002 Komatsu PC09-1 Mini Excavator

| Basic information | | | |
|--|---------------------------------------|---|---------------------------------------|
| Model | PC09-1 | Serial No. | 10423 |
| Product category | Mini Excavator | Manufacturer | Komatsu |
| Year of manufacture | 2002 | Working hours | 2726 hours |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Civil Engineering | Front Attachment | Standard |
| Type of Shoe | Rubber | Width of Track Shoe | 180 |
| Bucket Attachment | Standard | | |
| Appearance | | | |
| Engine Cover | Rusted / Corroded | Side Covers | Rusted / Corroded |
| Counter Weight | Scratched | Main Frame | Rusted / Corroded |
| Track Frame | Rusted / Corroded | Cabin | Rusted / Corroded |
| Interior | | | |
| Seat | Good Condition | | |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Moderate / within Service Limit |
| Traveling | Normal | Front Attachment | Normal |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Slight | Wear: Boom / Arm Joint Pin | Slight |
| Wear: Arm Tip Pin | Slight | Wear: Other Pins | Slight |
| Wear / Deformation: Bucket | Wear: Moderate / within Service Limit | Wear / Deformation: Blade | Wear: Moderate / within Service Limit |
| Undercarriage / Chassis / Tires | | | |
| Wear: Track Link Stretching (Right) | Slight | Wear: Track Link Stretching (Left) | Slight |
| Wear: Track Link Tread (Right) | Slight | Wear: Track Link Tread (Left) | Slight |
| Wear: Track Link Pins & Bushings (Right) | Slight | Wear: Track Link Pins & Bushings (Left) | Slight |
| Wear: Track Shoe / Rubber Shoe | Slight | Broken / Crack: Rubber Shoe (Right) | No |
| Broken / Crack: Rubber Shoe (Left) | No | Missing: Rubber Shoe Core | No |
| Wear: Lower Rollers | Slight | Oil Leak: Rollers | None |
| Broken / Missing: Rollers | None | Wear: Front Idler (Right) | Slight |
| Wear: Front Idler (Left) | Slight | Wear: Sprocket (Right) | Slight |
| Wear: Sprocket (Left) | Slight | Oil Leak: Travel Device | None |
| Oil Leak: Travel Pipes | None | | |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder | None |
| Oil Leak: Arm Cylinder | None | Oil Leak: Bucket Cylinder | None |
| Oil Leak: Swing Cylinder | None | Oil Leak: Blade Cylinder | None |
| Oil Leak: Engine | None | Oil Leak: Oil Cooler | None |
| Leak: Radiator | None | Leak: Cooling Pipes | None |
| Oil Leak: Fuel System | None | Oil Leak: Upper Structure | None |
| Oil Leak: Under Carriage | None | Oil Leak: Pilot Pipes | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Pump Device | None |

| | | | |
|-----------------------|-----------|------------------|---------------------------------|
| Overall Rating | | | |
| Appearance Evaluation | Repainted | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |