

1900 Komatsu CD60-1 Carrier

Basic information			
Model	CD60-1	Serial No.	1299
Product category	Carrier	Manufacturer	Komatsu
Year of manufacture	1900	Working hours	
Engine No.			
Detail Information			
Type of Shoe	Grouser	Loading platform type	Gravel carrier
Other	Heater	Main Frame	Good Condition
Appearance			
Track Frame	Good Condition	Cabin / Canopy	Rusted / Corroded
Door	Good Condition	Cabin Interior	Good Condition
Interior			
Seat	Torn	Console	Good Condition
Wear: Track Link Stretching (Right)	Slight		
Undercarriage / Chassis / Tires			
Fixation: Track shoe	No	Wear: Rubber Shoe	Moderate / within Service Limit
Wear: Pivot shaft	No	Broken / Missing: Rollers	No
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	No	Oil Leak: Travel Pipes	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Operation			
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	1 - 4 Pieces
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Pump Device	No
Oil Leak: Pilot Pipes	No	Engine	Normal
Exhaust Gas Color	Normal	Traveling	Normal
Dump cylinder (Right)	No	Break	Normal
Dump cylinder (Left)	No	Side Break	Normal
Oil Leak: Engine	No	Dumping	Normal
Other working device	Normal		
?? ? ??			
Vessel	Deformation: Moderate, Cracked, Repair Mark	Frame	Deformation: Moderate
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Heavy
Overall Rating	Fair		