## 2008 Hitachi ZX70-3 Hydraulic Excavator

Basic information			
Model	ZX70-3	Serial No.	80474
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Year of manufacture	2008	Working hours	7082 hours
Engine No.	296153		
Detail Information			
Job Status	Others	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Width of Track Shoe	450
Bucket Attachment	Wide Bucket, Fork	Other	Air Conditioner, Multi Lever
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Torn
Console	Faded	Air Conditioner	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucke	t Wear: Moderate / within Service L	imit	
Undercarriage / Chassis	/ Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Excessive / Required to replace
Broken / Missing: Rubber Pad	Broken / Missing (Left)  Moderate / within Service Limit	Missing: Rubber Pad Wear: Lower Rollers	more than 10 Pieces  Moderate / within Service Limit
Wear: Upper Rollers	Moderate / within Service Limit None	Broken / Missing: Rollers	Moderate / within Service Limit None
Jil I Dak. Hollare	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
	- woderate / Within OctVICE LITTIL	vveai. i folit fulet (Lett)	
Wear: Front Idler (Right)		Wear: Sprocket (Left)	Moderate / within Service Limit
Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left) Oil Leak: Travel Pipes	Moderate / within Service Limit None
Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device		Wear: Sprocket (Left) Oil Leak: Travel Pipes	Moderate / within Service Limit None
Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes	Moderate / within Service Limit		

Oil Leak: Arm Cylinder (Right)	None	Oil Leak: Bucket Cylinder (Right)	Excessive / Required to Repair
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	Slight Film	Oil Leak: Pilot Valve	Moderate Oozing
Oil Leak: Center Joint	None	Oil Leak: Swing Device	None
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		