2011 Hitachi ZX70-3 Hydraulic Excavator

Basic information			
Vodel	ZX70-3	Serial No.	81681
Product category	Hydraulic Excavator	Manufacturer	Hitachi
'ear of manufacture	2011	Working hours	5346 hours
Engine No.	256615		
Detail Information			
lob Status	Others	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Width of Track Shoe	450
Bucket Attachment	Wide Bucket	Other	Piping, EPA, Air Conditioner, Multi Lever
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Jnder Covers	Rusted / Corroded	Counter Weight	Scratched
Aain Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Frack Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Dirty
Console	Faded	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Fraveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Reinforcement
Near: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Near: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Near / Deformation: Bucket	Wear: Moderate / within Service Limit		
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Near: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Frack Shoe	No	Wear: Rubber Pad	Excessive / Required to replace
Broken / Missing: Rubber ^D ad	Broken / Missing (Left)	Missing: Rubber Pad	more than 10 Pieces
Near: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Dil Leak: Rollers	None	Broken / Missing: Rollers	None
Vear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Vear: Sprocket (Right) Dil Leak: Travel Device	Moderate / within Service Limit None	Wear: Sprocket (Left) Oil Leak: Travel Pipes	Moderate / within Service Limit None
Oil / Water / Air Leakage			
Oil / Water / Air Leakage Dil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None

Oil Leak: Arm Cylinder (Right)	None	Oil Leak: Bucket Cylinder (Right)	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	Slight Film	Oil Leak: Pilot Valve	Slight Film
Oil Leak: Center Joint	None	Oil Leak: Swing Device	None
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		