

## 2007 Hitachi ZX10U-2 Mini Excavator

Basic information			
Model	ZX10U-2	Serial No.	10328
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2007	Working hours	99999 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	No CAB/CNP
Front Attachment	Standard	Type of Shoe	Rubber
Width of Track Shoe	175	Bucket Attachment	Standard
Other	Piping, EPA, Multi Lever, Extended Truck Frame		
Appearance			
Engine Cover	Deformed / Dent	Side Covers	Rusted / Corroded
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Interior			
Seat	Good Condition	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	Moderate
Broken / Crack: Rubber Shoe (Left)	Moderate	Missing: Rubber Shoe Core	No
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	5 - 7 Pieces	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	Slight Film	Oil Leak: Boom Cylinder	Slight Film
Oil Leak: Arm Cylinder	Slight Film	Oil Leak: Bucket Cylinder	Slight Film
Oil Leak: Swing Cylinder	Slight Film	Oil Leak: Blade Cylinder	Slight Film
Oil Leak: Engine	Slight Film	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	Slight Film
Oil Leak: Upper Structure	None	Oil Leak: Under Carriage	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Heavy
Overall Rating	Fair		