## 2005 Hitachi ZX120 Hydraulic Excavator

Basic information			
Model	ZX120	Serial No.	69252
Product category	Hydraulic Excavator	Manufacturer	Hitachi
ear of manufacture	2005	Working hours	7348 hours
Engine No.	912553		
Detail Information			
lob Status	Rental	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
ype of Shoe	Grouser	Width of Track Shoe	500
Bucket Attachment	Standard	Other	Piping, EPA, Air Conditioner, Mult Lever
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Inder Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
rack Frame	Rusted / Corroded	Cabin	Glass: Missing
Door	Good Condition		
Interior			
Cabin Interior	Torn	Seat	Torn
Console	Faded	Air Conditioner	Good
	1 4404	7 iii Conditionor	0000
Operation	NI	Full access On a College	NI
ingine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing Front Attachment	Moderate / within Service Limit
raveling Pump Device	Normal Normal	Front Attachment	Normal
	Nomia		
Front & Pins			
Boom	Normal	Arm	Reinforcement
Vear: Boom Foot Pin	Moderate / within Service Limit		Moderate / within Service Limit
Vear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Vear / Deformation: Bucket	Wear: Excessive / Required to Repair		
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Vear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Vear: Track Link Tread Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Vear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Vear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Vear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Vear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None

Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	Slight Film	Oil Leak: Low Pressure Pipes	Slight Film
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	Slight Film
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		