2007 Hitachi ZX30UR-2 Mini Excavator

Basic information			
Model	ZX30UR-2	Serial No.	30490
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2007	Working hours	5232 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canopy
Cabin Type	ROPS	Front Attachment	Offset
Type of Shoe	Rubber	Width of Track Shoe	300
Bucket Attachment	Standard	Other	EPA, Multi Lever
Appearance		***************************************	
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Counter Weight	Scratched	Main Frame	Good Condition
Track Frame	Good Condition	Cabin	Rusted / Corroded
Interior			
Interior Cabin Interior	Good Condition	Seat	Torn
Console	Good Condition	Coat	1411
	Cook Condition		
Operation	N	F-110 0 1	NI1
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit		Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
wear / Deformation: Bucket	Wear: Moderate / within Service Limit		
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Excessive / Required to replace
Broken / Crack: Rubber Shoe (Right)	Moderate	Broken / Crack: Rubber Shoe (Left)	Moderate
Missing: Rubber Shoe Core	No	Wear: Upper Rollers	Moderate / within Service Limit
3		0"1	None
	Moderate / within Service Limit	Oil Leak: Rollers	110110
Wear: Lower Rollers	Moderate / within Service Limit None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Lower Rollers Broken / Missing: Rollers			
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	None Moderate / within Service Limit	Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit Moderate / within Service Limit
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes	None Moderate / within Service Limit Moderate / within Service Limit	Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit Moderate / within Service Limit
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil / Water / Air Leakage	None Moderate / within Service Limit Moderate / within Service Limit None	Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device	Moderate / within Service Limit Moderate / within Service Limit None
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil / Water / Air Leakage Oil Leak: Front Pipes	None Moderate / within Service Limit Moderate / within Service Limit None None	Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder	Moderate / within Service Limit Moderate / within Service Limit None
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder	None Moderate / within Service Limit Moderate / within Service Limit None None None	Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder	Moderate / within Service Limit Moderate / within Service Limit None None Slight Film
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder	None Moderate / within Service Limit Moderate / within Service Limit None None None None	Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder	Moderate / within Service Limit Moderate / within Service Limit None None Slight Film None
Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes	None Moderate / within Service Limit Moderate / within Service Limit None None None	Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder	Moderate / within Service Limit Moderate / within Service Limit None None Slight Film

Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		