1900 TCM 711 Wheel Loader

| Basic information | | | |
|---|---------------------------------|----------------------------------|---------------------------------|
| Model | 711 | Serial No. | 56U00263 |
| Product category | Wheel Loader | Manufacturer | TCM |
| ear of manufacture | 1900 | Working hours | 4168 hours |
| Engine No. | | | |
| Detail Information | | | |
| ob Status | Others | Type of Tire | Normal |
| icense Plate | No | Cabin / Canopy | Canopy |
| Power Transmission | | | |
| System | HST | Drive System | All Wheel Drive |
| Size of Tire | 12-16.5 | Bucket Attachment | Loading BK |
| Appearance | | | |
| Main Frame | Rusted / Corroded | Front Frame | Rusted / Corroded |
| Counter Weight | Scratched | Cabin | Rusted / Corroded |
| Interior | | | |
| Seat | Torn | Console | Malfunction |
| Jeal | TOTAL | COHSOIC | IVIAIIUIICIIOII |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Γraveling | Normal | HST Motor | Normal |
| Front Attachment | Normal | Pump Device | Normal |
| Steering | Normal | Break | Normal |
| Side Break | Poor Operation | | |
| Front & Pins | | | |
| Lift(Push)Arm | Normal | Wear: Front Pins & Bushings | Moderate / within Service Limit |
| Wear: Bucket Pins & Bushings | Heavy | Wear: Bucket Side Plate | Excessive / Required to replace |
| Wear: Bucket Lip | Excessive / Required to replace | Wear: Bucket Bottom Plate | Excessive / Required to replace |
| Wear: Tooth / Cutting Edges | Moderate / within Service Limit | | |
| Undercarriage / Chassis / | Tires | | |
| Scratches: Tire (Front- Right Wheel) | Slight | Wear: Tire (Front-Right wheel) | Excessive / Required to replace |
| Scratches: Tire (Front-Left Wheel) | Slight | Wear: Tire (Front-Left Wheel) | Excessive / Required to replace |
| Scratches: Tire (Rear-Right Wheel) | Slight | Wear: Tire (Rear-Right Wheel) | Excessive / Required to replace |
| Scratches: Tire (Rear-Left Wheel) | Slight | Wear: Tire (Rear-Left Wheel) | Excessive / Required to replace |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Lift Cylinder (Right) | None |
| Oil Leak: Lift Cylinder (Left) | None | Oil Leak: Bucket Cylinder | None |
| Oil Leak: Engine | Slight Film | Oil Leak: Oil Cooler | None |
| _eak: Radiator | None | Leak: Cooling Pipes | None |
| Oil Leak: Fuel System | None | Oil Leak: Control Valve | None |
| Dil Leak: Low Pressure Pipes | None | Oil Leak: High Pressure Pipes | None |
| Oil Leak: Pilot Pipes | None | Oil Leak: Pilot Valve | None |
| Oil Leak: Pump Device | Slight Film | | |

| Overall Rating | | | |
|-----------------------|------|------------------|---------------------------------|
| Appearance Evaluation | Fair | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |