1900 Hitachi EX60-2 Hydraulic Excavator

Basic information			
Model	EX60-2	Serial No.	36417
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Year of manufacture	1900	Working hours	5850 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canany	Cabin
Front Attachment	Civil Engineering Standard	Cabin / Canopy Type of Shoe	Grouser
Width of Track Shoe	450	Bucket Attachment	Standard
	430	Ducket Attachment	Staticato
Appearance		2	
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Latch Malfunction		
Interior			
Cabin Interior	Defect / Missing	Seat	Torn
Console	Faded		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Poor Combined Operation
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Deformed / Dent
Wear: Boom Foot Pin	Heavy	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Near / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link	Slight
		Stretching (Right)	<u> </u>
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins &		Wear: Track Shoe / Rubber	O. 1.
Bushings (Left)	Slight	Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Arm Cylinder (Right)	None	Oil Leak: Bucket Cylinder (Right)	None
			Cliabt Film
	None	Oil Leak: Engine	Slight Film
Oil Leak: Blade Cylinder Oil Leak: Oil Cooler	None None	Oil Leak: Engine Leak: Radiator	Slight Film None

Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	Slight Film
Oil Leak: Pilot Valve	Slight Film	Oil Leak: Center Joint	Slight Film
Oil Leak: Swing Device	Slight Film	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Usable		