1999 Hitachi LX30-3 Wheel Loader

| Basic information | | | | |
|---|---------------------------------|-------------------------------------|---------------------------------|--|
| Model | LX30-3 | Serial No. | 5763 | |
| Product category | Wheel Loader | Manufacturer | Hitachi | |
| Year of manufacture | 1999 | Working hours | 2952 hours | |
| Engine No. | | | | |
| Detail Information | | | | |
| Job Status | Rental | Type of Tire | Normal | |
| Cabin / Canopy | Canopy | Cabin Type | Standard | |
| Power Transmission System | нѕт | Drive System | All Wheel Drive | |
| Size of Tire | 15.5/70-18-8PR | Bucket Attachment | Loading BK | |
| Appearance | | | | |
| Main Frame | Good Condition | Front Frame | Good Condition | |
| Counter Weight | Scratched | Cabin | Deformed / Dent | |
| Interior | | | | |
| Seat | Required to Repair / Replace | Console | Broken | |
| | required to Repail / Replace | OUISOIG | DIONGII | |
| Operation | | | | |
| Engine | Normal | Exhaust Gas Color | Normal | |
| Traveling | Normal | Clutch | Normal | |
| HST Motor | Normal | Front Attachment | Normal | |
| Pump Device | Normal | Steering | Normal | |
| Break | Normal | Side Break | Normal | |
| Front & Pins | | | | |
| Lift(Push)Arm | Normal | Bellcrank | Normal | |
| Wear: Front Pins & Bushings | Slight | Wear: Bucket Pins & Bushings | Slight | |
| Wear: Center Pins | Slight | Wear: Bucket Side Plate | Moderate / within Service Limit | |
| Wear: Bucket Lip | Moderate / within Service Limit | Wear: Bucket Bottom Plate | Moderate / within Service Limit | |
| Wear: Tooth / Cutting Edges | Moderate / within Service Limit | | | |
| Undercarriage / Chassis / | Tires | | | |
| Scratches: Tire (Front- Right Wheel) | Slight | Wear: Tire (Front-Right wheel) | Moderate / within Service Limit | |
| Scratches: Tire (Front-Left Wheel) | Slight | Wear: Tire (Front-Left Wheel) | Moderate / within Service Limit | |
| Scratches: Tire (Rear-Right Wheel) | Slight | Wear: Tire (Rear-Right Wheel) | Moderate / within Service Limit | |
| Scratches: Tire (Rear-Left Wheel) | Slight | Wear: Tire (Rear-Left Wheel) | Moderate / within Service Limit | |
| Oil Leak: Axle | No | Oil Leak: Differential Gear Case | No | |
| Oil / Water / Air Leakage | | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Lift Cylinder (Right) | None | |
| Oil Leak: Lift Cylinder (Left) | None | Oil Leak: Bucket Cylinder | None | |
| Oil Leak: Steering Cylinder | None | Oil Leak: Engine | None | |
| Oil Leak: Oil Cooler | None | Leak: Radiator | None | |
| Leak: Cooling Pipes | None | Oil Leak: Fuel System | None | |
| Oil Leak: Control Valve | None | Oil Leak: Low Pressure Pipes | None | |

| Oil Leak: High Pressure Pipes | None | Oil Leak: Pump Device | None | |
|----------------------------------|------|-----------------------|--------|--|
| Oil Leak: Transmission / Torcon | None | | | |
| Overall Rating | | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Slight | |
| Overall Pating | Fair | | | |