2007 Hitachi ZX135US Hydraulic Excavator

D				
Basic information	77405110	0 : 111	74040	
Model	ZX135US	Serial No.	74942	
Product category	Hydraulic Excavator	Manufacturer	Hitachi	
Year of manufacture	2007	Working hours	10737 hours	
Engine No.				
Detail Information				
Job Status	Rental	Cabin / Canopy	Cabin	
Front Attachment	Standard	Type of Shoe	Grouser with Pad	
Width of Track Shoe	500	Bucket Attachment	Standard	
Other	Piping, EPA, Air Conditioner, Multi Lever			
Appearance				
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded	
Under Covers	Rusted / Corroded	Counter Weight	Scratched	
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded	
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded	
Door	Good Condition			
Interior				
Cabin Interior	Good Condition	Seat	Torn	
Console	Good Condition	Air Conditioner	Malfunction	
<u> </u>				
Operation		E.L. (C. C.)	N	
Engine	Normal	Exhaust Gas Color	Normal	
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit	
Traveling	Normal	Front Attachment	Normal	
Pump Device	Normal			
Front & Pins				
Boom	Normal	Arm	Reinforcement	
Wear: Boom Foot Pin	Heavy	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit	
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy	
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Deformation: Heavy	
Undercarriage / Chassis /	Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight	
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Excessive / Required to replace	
Wear: Track Link Tread (Left)	Excessive / Required to replace	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit	
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	
Bent / Broken / Missing: Track Shoe	more than 10 Pieces	Wear: Rubber Pad	Excessive / Required to replace	
Broken / Missing: Rubber Pad	Broken / Missing (Left)	Missing: Rubber Pad	more than 10 Pieces	
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit	
Oil Leak: Rollers	None	Broken / Missing: Rollers	None	
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit	
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight	
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None	
Oil / Water / Air Leakage				
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None	

Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	Slight Film	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	None	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	Slight Film	Oil Leak: Pilot Valve	Slight Film
Oil Leak: Center Joint	None	Oil Leak: Swing Device	None
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		