1987 TCM 820 Wheel Loader

| Model | 820 | Serial No. | 62710806 | |
|---|---------------------------------|-------------------------------------|---------------------------------|--|
| Product category | Wheel Loader | Manufacturer | TCM | |
| ear of manufacture | 1987 | Working hours | 3816 hours | |
| Engine No. | | | | |
| Detail Information | | | | |
| ob Status | Civil Engineering | Type of Tire | Normal | |
| Cabin / Canopy | Cabin | Power Transmission System | Torque Converter | |
| Orive System | All Wheel Drive | Bucket Attachment | Loading BK | |
| Appearance | | | | |
| Main Frame | Good Condition | Front Frame | Good Condition | |
| Counter Weight | Good Condition | Cabin | Rusted / Corroded | |
|)oor | Not Closed Properly | | | |
| Interior | | | | |
| Cabin Interior | Torn | Seat | Torn | |
| Console | Missing | | | |
| Operation | | | | |
| Engine | Normal | Exhaust Gas Color | Normal | |
| raveling | Normal | Transmission / Torque Converter | Normal | |
| Clutch | Normal | HST Motor | Normal | |
| ront Attachment | Normal | Pump Device | Normal | |
| Steering | Normal | Break | Normal | |
| Side Break | Poor Operation | | | |
| Front & Pins | | | | |
| .ift(Push)Arm | Normal | Bellcrank | Normal | |
| Vear: Front Pins & | Moderate / within Service Limit | Wear: Bucket Pins & Bushings | Moderate / within Service Limit | |
| Vear: Center Pins | Moderate / within Service Limit | Wear: Bucket Side Plate | Excessive / Required to replace | |
| Vear: Bucket Lip | Moderate / within Service Limit | | Excessive / Required to replace | |
| Vear: Tooth / Cutting Edges | Moderate / within Service Limit | | | |
| Undercarriage / Chassis / | Tires | | | |
| Scratches: Tire (Front- Right Wheel) | Slight | Wear: Tire (Front-Right wheel) | Moderate / within Service Limit | |
| Caratabas: Tira (Frant Laft | Slight | Wear: Tire (Front-Left Wheel) | Moderate / within Service Limit | |
| Scratches: Tire (Rear-Right Vheel) | Moderate / within Service Limit | Wear: Tire (Rear-Right Wheel) | Moderate / within Service Limit | |
| Scratches: Tire (Rear-Left Vheel) | Moderate / within Service Limit | Wear: Tire (Rear-Left Wheel) | Moderate / within Service Limit | |
| Dil Leak: Axle | No | Oil Leak: Differential Gear Case | No | |
| Oil / Water / Air Leakage | | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Lift Cylinder (Right) | None | |
| Oil Leak: Lift Cylinder (Left) | None | Oil Leak: Bucket Cylinder | None | |
| Oil Leak: Steering Cylinder | None | Oil Leak: Engine | None | |
| Oil Leak: Oil Cooler | None | Leak: Radiator | None | |
| eak: Cooling Pipes | None | Oil Leak: Fuel System | None | |

| Oil Leak: Control Valve | None | Oil Leak: Low Pressure Pipes | None | |
|------------------------------------|------|---------------------------------|-------|--|
| Oil Leak: High Pressure Pipes | None | Oil Leak: Pump Device | None | |
| Oil Leak: Transmission / Torcon | None | | | |
| Overall Rating | | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Heavy | |
| Overall Rating | Fair | | | |