2007 Hitachi ZX40UR-2D Mini Excavator

Basic information			
Model	ZX40UR-2D	Serial No.	50027
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2007	Working hours	4005 hours
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Canany
Front Attachment	Offset	Type of Shoe	Canopy Grouser with Pad
Width of Track Shoe	300	Bucket Attachment	Standard
Other	EPA, Multi Lever, Arm Crane	Ducket Attachment	Otalidaid
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Jnder Covers	Rusted / Corroded	Counter Weight	Scratched
Гrack Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Interior			
Seat	Torn	Console	Good Condition
Operation			
	Normal	Exhaust Gas Color	Normal
Engine Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
	Nomia	1 TOTA Attachinient	Nomia
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit		Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link	Moderate
Deize. Hack Liliks	INO	Stretching (Right)	Moderate
Wear: Track Link	Moderate	Wear: Track Link Tread	Moderate / within Service Limit
Stretching (Left)		(Right)	
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins &		Wear: Track Shoe / Rubber	
Bushings (Left)	Moderate / within Service Limit	Shoe	Moderate / within Service Limit
Bent / Broken / Missing:	No	Wear: Rubber Pad	Evansive / Required to replace
Track Shoe	INO	Wear. Rubber Fau	Excessive / Required to replace
Broken / Missing: Rubber	No	Wear: Upper Rollers	Moderate / within Service Limit
Pad			
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit Moderate / within Service Limit	Wear: Sprocket (Right) Oil Leak: Travel Device	Moderate / within Service Limit None
Dil Leak: Travel Pipes	None	Oli Leak. Havel Device	INOILE
	NOTIC		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
_eak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None

Oil Leak: Under Carriage	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		