## 2010 Hitachi ZX200-3 Hydraulic Excavator

Basic information			
Model	ZX200-3	Serial No.	216543
Product category	Hydraulic Excavator	Manufacturer	Hitachi
ear of manufacture	2010	Working hours	4302 hours
Engine No.	473014		
Detail Information			
lob Status	Others	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
ype of Shoe	Grouser	Width of Track Shoe	600
Bucket Attachment	Standard	Other	Piping, EPA, Air Conditioner, Mult Lever
Appearance			
	Good Condition	Side Covers	Rusted / Corroded
7	Rusted / Corroded	Counter Weight	Scratched
/lain Frame	Rusted / Corroded	D Frame	Rusted / Corroded
	Rusted / Corroded	Cabin	Good Condition
	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Burned by Cigarette
Console	Faded	Air Conditioner	Good
Operation			
	Normal	Exhaust Gas Color	Normal
	Normal	Wear: Swing Bearing	Moderate / within Service Limit
	Normal	Front Attachment	Normal
	Normal	1 TOTE / Machinett	Normal
Front & Pins			
	Normal	Arm	Reinforcement
	Moderate / within Service Limit		Moderate / within Service Limit
	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Vear / Deformation: Bucket		Wear. Other First	Moderate / Within Dervice Limit
Undercarriage / Chassis /	Tires		
······	No	Wear: Track Link	Slight
		Stretching (Right)	~
stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
N/ T		14/ T       D: 0	
Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Left) Vear: Track Link Pins &	Moderate / within Service Limit  Moderate / within Service Limit		Moderate / within Service Limit  Moderate / within Service Limit
Left) Vear: Track Link Pins & Bushings (Left) Bent / Broken / Missing:		Bushings (Right) Wear: Track Shoe / Rubber	
Left) Vear: Track Link Pins & ushings (Left) ent / Broken / Missing: rack Shoe Vear: Lower Rollers	Moderate / within Service Limit	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers Oil Leak: Rollers	Moderate / within Service Limit
Left) Vear: Track Link Pins & ushings (Left) ent / Broken / Missing: rack Shoe Vear: Lower Rollers	Moderate / within Service Limit 1 - 4 Pieces	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers	Moderate / within Service Limit  Moderate / within Service Limit
Left) Vear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left)	Moderate / within Service Limit  1 - 4 Pieces  Moderate / within Service Limit  None  Moderate / within Service Limit	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit  Moderate / within Service Limit  None
Left) Vear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left)	Moderate / within Service Limit  1 - 4 Pieces  Moderate / within Service Limit  None	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right)	Moderate / within Service Limit  Moderate / within Service Limit  None  Moderate / within Service Limit
Left) Vear: Track Link Pins & Bushings (Left) Sent / Broken / Missing: Track Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left)	Moderate / within Service Limit  1 - 4 Pieces  Moderate / within Service Limit  None  Moderate / within Service Limit	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit
Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Frack Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit  1 - 4 Pieces  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit
Left) Vear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left) Dil Leak: Travel Pipes Oil / Water / Air Leakage	Moderate / within Service Limit  1 - 4 Pieces  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit	Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit

Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		