## 1997 Hitachi LX70-2C Wheel Loader

Basic information			
Model	LX70-2C	Serial No.	3271
Product category	Wheel Loader	Manufacturer	Hitachi
Year of manufacture	1997	Working hours	4447 hours (Estimated)
Engine No.			
Detail Information			
Job Status	Rental	Type of Tire	Normal
Cabin / Canopy	Canopy	Power Transmission System	HST
Orive System	All Wheel Drive	Size of Tire	16.9-24-10PR
Bucket Attachment	Loading BK		
Appearance			
Main Frame	Rusted / Corroded	Front Frame	Rusted / Corroded
Counter Weight	Scratched	Cabin	Rusted / Corroded
Interior			
Seat	Torn	Console	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Fraveling	Normal	HST Motor	Normal
Front Attachment	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Side Break	Normal		
Front & Pins			
_ift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Moderate / within Service Limit	Wear: Bucket Pins & Bushings	Moderate / within Service Limit
Near: Center Pins	Moderate / within Service Limit	Wear: Bucket Side Plate	Excessive / Required to replace
Vear: Bucket Lip	Excessive / Required to replace	Wear: Bucket Bottom Plate	Excessive / Required to replace
Wear: Tooth / Cutting Edges	Excessive / Required to replace		
Undercarriage / Chassis /	Tires		
Scratches: Tire (Front- Right Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Right wheel)	Moderate / within Service Limit
Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Left Wheel)	Moderate / within Service Limit
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
	None	Oil Leak: Lift Cylinder	None
······ <del>·</del>	None	(Right)	
Dil Leak: Front Pipes	None	Oil Leak: Bucket Cylinder	None
Dil Leak: Front Pipes Dil Leak: Lift Cylinder (Left)			None Slight Film
Dil Leak: Front Pipes Dil Leak: Lift Cylinder (Left) Dil Leak: Steering Cylinder	None	Oil Leak: Bucket Cylinder	
Dil Leak: Front Pipes Dil Leak: Lift Cylinder (Left) Dil Leak: Steering Cylinder Dil Leak: Oil Cooler	None None	Oil Leak: Bucket Cylinder Oil Leak: Engine	Slight Film

Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	Slight Film
Oil Leak: Transmission / Torcon	Slight Film		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		