2006 Hitachi ZX75US-A Hydraulic Excavator

| Basic information | | | |
|--|---------------------------------|--|--|
| Model | ZX75US-A | Serial No. | 44151 |
| Product category | Hydraulic Excavator | Manufacturer | Hitachi |
| ear of manufacture | 2006 | Working hours | |
| Engine No. | | | |
| Detail Information | | | |
| lob Status | Rental | Cabin / Canopy | Cabin |
| Front Attachment | Standard | Type of Shoe | Grouser with Pad |
| Bucket Attachment | Standard | Other | Blade, Air Conditioner, Multi Level Arm Crane |
| Appearance | | | |
| Engine Cover | Rusted / Corroded | Side Covers | Rusted / Corroded |
| Jnder Covers | Rusted / Corroded | Counter Weight | Scratched |
| Main Frame | Rusted / Corroded | D Frame | Rusted / Corroded |
| Frack Frame | Rusted / Corroded | Cabin | Rusted / Corroded |
| Door | Good Condition | | |
| Interior | | | |
| Cabin Interior | Good Condition | Seat | Torn |
| Console | Missing | Air Conditioner | Good |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Moderate / within Service Limit |
| Fraveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | |
| Front & Pins | | | |
| Boom | Normal | Arm | Deformed / Dent |
| Wear: Boom Foot Pin | Moderate / within Service Limit | Wear: Boom / Arm Joint Pin | Moderate / within Service Limit |
| Near: Arm Tip Pin | Moderate / within Service Limit | Wear: Other Pins | Moderate / within Service Limit |
| Near / Deformation: Bucke | et Deformation: Moderate | Wear / Deformation: Blade | Deformation: Moderate |
| Undercarriage / Chassis | / Tires | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Moderate |
| Wear: Track Link Stretching (Left) | Moderate | Wear: Track Link Tread (Right) | Moderate / within Service Limit |
| Vear: Track Link Tread Left) | Moderate / within Service Limit | Wear: Track Link Pins & Bushings (Right) | Moderate / within Service Limit |
| Vear: Track Link Pins & Bushings (Left) | Moderate / within Service Limit | Wear: Track Shoe / Rubber Shoe | Moderate / within Service Limit |
| Bent / Broken / Missing: Frack Shoe | No | Wear: Rubber Pad | Moderate / within Service Limit |
| Broken / Missing: Rubber Pad | No | Missing: Rubber Pad | No |
| Vear: Upper Rollers | Moderate / within Service Limit | Wear: Lower Rollers | Moderate / within Service Limit |
| Dil Leak: Rollers | None | Broken / Missing: Rollers | None |
| Vear: Front Idler (Right) | Moderate / within Service Limit | Wear: Front Idler (Left) | Moderate / within Service Limit |
| Wear: Sprocket (Right) | Moderate / within Service Limit | Wear: Sprocket (Left) | Moderate / within Service Limit |
| Oil Leak: Travel Device | None | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder (Right) | None |
| | | | |

| Oil Leak: Arm Cylinder (Right) | None | Oil Leak: Bucket Cylinder (Right) | Moderate Oozing |
|----------------------------------|-----------|-----------------------------------|---------------------------------|
| Oil Leak: Blade Cylinder | None | Oil Leak: Engine | None |
| Oil Leak: Oil Cooler | None | Leak: Radiator | None |
| Leak: Cooling Pipes | None | Oil Leak: Fuel System | None |
| Oil Leak: Control Valve | None | Oil Leak: Low Pressure Pipes | Slight Film |
| Oil Leak: High Pressure Pipes | None | Oil Leak: Pilot Pipes | Slight Film |
| Oil Leak: Pilot Valve | None | Oil Leak: Center Joint | None |
| Oil Leak: Swing Device | None | Oil Leak: Pump Device | None |
| Overall Rating | | | |
| Appearance Evaluation | Repainted | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |