

2007 Hitachi ZX40UR-2 Mini Excavator

| Basic information | | | |
|-------------------------------------|---------------------------------------|-------------------------------------|---------------------------------------|
| Model | ZX40UR-2 | Serial No. | 30272 |
| Product category | Mini Excavator | Manufacturer | Hitachi |
| Year of manufacture | 2007 | Working hours | 3213 hours |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Rental | Cabin / Canopy | Canopy |
| Front Attachment | Offset | Type of Shoe | Rubber |
| Width of Track Shoe | 300 | Bucket Attachment | Standard |
| Other | EPA, Multi Lever | | |
| Appearance | | | |
| Engine Cover | Rusted / Corroded | Side Covers | Rusted / Corroded |
| Under Covers | Rusted / Corroded | Counter Weight | Rusted / Corroded |
| Main Frame | Rusted / Corroded | Track Frame | Rusted / Corroded |
| Cabin | Rusted / Corroded | | |
| Interior | | | |
| Seat | Dirty | Console | Faded |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Excessive / Required to Repair |
| Traveling | Normal | Front Attachment | Normal |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Heavy | Wear: Boom / Arm Joint Pin | Heavy |
| Wear: Arm Tip Pin | Heavy | Wear: Other Pins | Heavy |
| Wear / Deformation: Bucket | Wear: Moderate / within Service Limit | Wear / Deformation: Blade | Wear: Moderate / within Service Limit |
| Undercarriage / Chassis / Tires | | | |
| Wear: Track Link Stretching (Right) | Slight | Wear: Track Link Stretching (Left) | Slight |
| Wear: Track Link Tread (Right) | Moderate / within Service Limit | Wear: Track Link Tread (Left) | Moderate / within Service Limit |
| Wear: Track Shoe / Rubber Shoe | Excessive / Required to replace | Broken / Crack: Rubber Shoe (Right) | Moderate |
| Broken / Crack: Rubber Shoe (Left) | No | Missing: Rubber Shoe Core | No |
| Wear: Upper Rollers | Moderate / within Service Limit | Wear: Lower Rollers | Moderate / within Service Limit |
| Oil Leak: Rollers | None | Broken / Missing: Rollers | None |
| Wear: Front Idler (Right) | Moderate / within Service Limit | Wear: Front Idler (Left) | Moderate / within Service Limit |
| Wear: Sprocket (Right) | Moderate / within Service Limit | Wear: Sprocket (Left) | Moderate / within Service Limit |
| Oil Leak: Travel Device | None | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder | None |
| Oil Leak: Arm Cylinder | None | Oil Leak: Bucket Cylinder | None |
| Oil Leak: Offset Cylinder | None | Oil Leak: Blade Cylinder | None |
| Oil Leak: Engine | None | Oil Leak: Oil Cooler | None |
| Leak: Radiator | Slight Film | Leak: Cooling Pipes | None |
| Oil Leak: Fuel System | None | Oil Leak: Upper Structure | None |
| Oil Leak: Under Carriage | None | Oil Leak: Pilot Pipes | None |
| Oil Leak: Pilot Valve | None | Oil Leak: Pump Device | None |

| | | | |
|-----------------------|------|------------------|---------------------------------|
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |