2004 Hitachi ZX75US-A Hydraulic Excavator

Basic information			
Model	ZX75US-A	Serial No.	41987
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Year of manufacture	2004	Working hours	4560 hours
Engine No.	257738		
Detail Information			
Job Status	Rental	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Width of Track Shoe	450
Bucket Attachment	Standard	Other	EPA, Air Conditioner, Multi Lever Arm Crane
Appearance			
Engine Cover	Deformed / Dent	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Dirty
Console	Faded	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal	1 Tork / kladimion	The state of the s
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit		Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
· · · · · · · · · · · · · · · · · · ·	Wear: Moderate / within Service Li		Woderate / Within Gervice Limit
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Moderate / within Service Limit
Broken / Missing: Rubber Pad	Broken / Missing (Left)	Missing: Rubber Pad	1 - 4 Pieces
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	1 - 4 Pieces	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	Slight Film
Oil / Water / Air Leakage			
		Oil Leak: Boom Cylinder	

Oil Leak: Arm Cylinder (Right)	None	Oil Leak: Bucket Cylinder (Right)	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Control Valve	Slight Film
Oil Leak: Low Pressure Pipes	Slight Film	Oil Leak: High Pressure Pipes	Slight Film
Oil Leak: Pilot Pipes	Slight Film	Oil Leak: Pilot Valve	Slight Film
Oil Leak: Center Joint	Slight Film	Oil Leak: Swing Device	Slight Film
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		