2006 Hitachi ZX30UR-2 Mini Excavator

Basic information			
Model	ZX30UR-2	Serial No.	30337
Product category	Mini Excavator	Manufacturer	Hitachi
ear of manufacture	2006	Working hours	4038 hours
Engine No.			
Detail Information			
	Dantal	O-h:- / O	Oabia
Job Status	Rental	Cabin / Canopy	Cabin
Front Attachment Width of Track Shoe	Standard	Type of Shoe	Grouser with Pad
Other	300	Bucket Attachment	Standard
Julei	EPA, Multi Lever		
Appearance			
Engine Cover	Good Condition	Side Covers	Good Condition
Inder Covers	Good Condition	Counter Weight	Good Condition
//ain Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition		
Interior			
Seat	Torn	Console	Good Condition
	TUIT	COLISOIG	Good Condition
Operation			
Ingine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
raveling	Normal	Front Attachment	Normal
Front & Pins			
	Normal	Arm	Normal
Boom		Arm	
Vear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	
Vear: Arm Tip Pin Vear / Deformation: Bucke	Slight	Wear: Other Pins	Slight
vear / Deformation. Bucke	t G000	Wear / Deformation: Blade	INOTTIAL
Undercarriage / Chassis	/ Tires		
Seize: Track Links	No	Wear: Track Link	Slight
A/ T		Stretching (Right)	
Vear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread		Wear: Track Link Pins &	
Left)	Slight	Bushings (Right)	Slight
Wear: Track Link Pins &	Cliebs	Maari Traak Chaa / Dubhar	Olimba
	Slight	Shoe	Slight
Bushings (Left)		SHOE	
Bent / Broken / Missing:	No	31106	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Slight
Bent / Broken / Missing: Frack Shoe Vear: Lower Rollers	Slight	Wear: Upper Rollers Oil Leak: Rollers	None
Bent / Broken / Missing: Track Shoe Vear: Lower Rollers Broken / Missing: Rollers	Slight None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right)	None Slight
Bent / Broken / Missing: Frack Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left)	Slight None Slight	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	None Slight Slight
Sent / Broken / Missing: Frack Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left)	Slight None Slight Slight	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right)	None Slight
Sent / Broken / Missing: Frack Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left)	Slight None Slight	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	None Slight Slight
Bent / Broken / Missing: Frack Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left)	Slight None Slight Slight None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	None Slight Slight
Bent / Broken / Missing: Frack Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Dil Leak: Travel Pipes Oil / Water / Air Leakage	Slight None Slight Slight None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device	None Slight Slight None
Bent / Broken / Missing: Frack Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left) Dil Leak: Travel Pipes Oil / Water / Air Leakage	Slight None Slight Slight None None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder	None Slight Slight None
Bent / Broken / Missing: Frack Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Dil Leak: Travel Pipes Oil / Water / Air Leakage Dil Leak: Arm Cylinder	Slight None Slight Slight None None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder	None Slight Slight None None
Bent / Broken / Missing: Frack Shoe Vear: Lower Rollers Broken / Missing: Rollers Vear: Front Idler (Left) Vear: Sprocket (Left) Dil Leak: Travel Pipes Oil / Water / Air Leakage Dil Leak: Front Pipes Dil Leak: Arm Cylinder Dil Leak: Offset Cylinder	Slight None Slight Slight None None None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder	None Slight Slight None None None None
Bent / Broken / Missing: Frack Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Dil Leak: Travel Pipes Dil Leak: Front Pipes Dil Leak: Arm Cylinder Dil Leak: Offset Cylinder Dil Leak: Engine	Slight None Slight Slight None None None None None None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder Oil Leak: Oil Cooler	None Slight Slight None None None None None None
Bent / Broken / Missing: Frack Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Dil Leak: Travel Pipes	Slight None Slight Slight None None None	Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder	None Slight Slight None None None None

Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		