2008 Hitachi ZX40UR-2D Mini Excavator

| Basic information | | | |
|--|---------------------------------------|--|--------------------------------------|
| Model | ZX40UR-2D | Serial No. | 50034 |
| Product category | Mini Excavator | Manufacturer | Hitachi |
| Year of manufacture | 2008 | Working hours | |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Rental | Cabin / Canopy | Canopy |
| | Standard | Front Attachment | Offset, Standard |
| | Grouser with Pad | Bucket Attachment | Standard |
| Appearance | | | |
| | Good Condition | Side Covers | Good Condition |
| | Good Condition | Counter Weight | Good Condition |
| | Good Condition | Track Frame | Good Condition |
| | Good Condition | TIACK FIAITIE | Good Coridition |
| | Good Condition | | |
| Interior | One di One dition | 0 | |
| | Good Condition | Seat | Good Condition |
| Console | Good Condition | | |
| Operation | | 12.0 | |
| | Normal | Exhaust Gas Color | Normal |
| | Normal | Wear: Swing Bearing | Slight |
| Traveling | Normal | Front Attachment | Normal |
| Front & Pins | | | |
| Boom | Normal | Arm | Normal |
| Wear: Boom Foot Pin | Moderate / within Service Limit | Wear: Boom / Arm Joint Pin | Moderate / within Service Limit |
| Wear: Arm Tip Pin | Moderate / within Service Limit | Wear: Other Pins | Moderate / within Service Limit |
| Wear / Deformation: Bucket | Wear: Moderate / within Service Limit | Wear / Deformation: Blade | Wear: Moderate / within Service Limi |
| Undercarriage / Chassis / | Tires | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Moderate |
| Wear: Track Link Stretching (Left) | Moderate | Wear: Track Link Tread (Right) | Moderate / within Service Limit |
| Wear: Track Link Tread (Left) | Moderate / within Service Limit | Wear: Track Link Pins & Bushings (Right) | Moderate / within Service Limit |
| Wear: Track Link Pins & Bushings (Left) | Moderate / within Service Limit | Wear: Rubber Pad | Moderate / within Service Limit |
| Broken / Missing: Rubber Pad | No | Missing: Rubber Pad | No |
| Wear: Upper Rollers | Moderate / within Service Limit | Wear: Lower Rollers | Moderate / within Service Limit |
| Oil Leak: Rollers | None | Broken / Missing: Rollers | None |
| Wear: Front Idler (Right) | Moderate / within Service Limit | Wear: Front Idler (Left) | Moderate / within Service Limit |
| · · · · · · · · · · · · · · · · · · · | Moderate / within Service Limit | Wear: Sprocket (Left) | Moderate / within Service Limit |
| Oil Leak: Travel Device | None | Oil Leak: Travel Pipes | None |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder | None |
| Oil Leak: Arm Cylinder | None | Oil Leak: Bucket Cylinder | None |
| Oil Leak: Offset Cylinder | None | Oil Leak: Blade Cylinder | None |
| Oil Leak: Engine | None | Oil Leak: Oil Cooler | None |
| | None | Leak: Cooling Pipes | None |
| Oil Leak: Fuel System | None | Oil Leak: Upper Structure | None |
| On Loak. I doi Oystoni | | | |

| Oil Leak: Pilot Valve | None | Oil Leak: Pump Device | None |
|-----------------------|------|-----------------------|---------------------------------|
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |