2007 Hitachi ZX200-3 Hydraulic Excavator

Basic information			
Model	ZX200-3	Serial No.	205402
Product category	Hydraulic Excavator	Manufacturer	Hitachi
Year of manufacture	2007	Working hours	
Engine No.			
Detail Information			
Job Status	Rental	Cabin / Canopy	Cabin
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Grouser	Bucket Attachment	Standard
Other	Piping, EPA, Air Conditioner, Multi Lever		
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Torn
Console	Faded	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Dinc			
Front & Pins			
	Normal	Arm	Normal
Boom	Normal Moderate / within Service Limit		Normal Moderate / within Service Limit
Boom Wear: Boom Foot Pin			
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins	Moderate / within Service Limit
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim	Wear: Boom / Arm Joint Pin Wear: Other Pins	Moderate / within Service Limit
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis /	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim	Wear: Boom / Arm Joint Pin Wear: Other Pins	Moderate / within Service Limit
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link	Moderate / within Service Limit Heavy
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread	Moderate / within Service Limit Heavy
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins &	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins &	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit Moderate / within Service Limit
Wear: Boom Foot Pin Wear: Arm Tip Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit
Wear: Boom Foot Pin Wear: Arm Tip Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers Oil Leak: Rollers	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit
Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit None	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Lower Rollers Broken / Missing: Rollers	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit None Moderate / within Service Limit
Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit None Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit None Moderate / within Service Limit
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit None Moderate / within Service Limit Excessive / Required to replace
Boom Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit None Moderate / within Service Limit Excessive / Required to replace
Wear: Boom Foot Pin Wear: Arm Tip Pin Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage	Moderate / within Service Limit Moderate / within Service Limit Wear: Moderate / within Service Lim Tires No Slight Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit None Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None Moderate / within Service Limit None	Wear: Boom / Arm Joint Pin Wear: Other Pins it Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes	Moderate / within Service Limit Heavy Slight Moderate / within Service Limit None Moderate / within Service Limit None Moderate / within Service Limit Excessive / Required to replace None

Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	Moderate Oozing	Oil Leak: Low Pressure Pipes	Moderate Oozing
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	Moderate Oozing
Oil Leak: Pilot Valve	Moderate Oozing	Oil Leak: Center Joint	Slight Film
Oil Leak: Swing Device	None	Oil Leak: Pump Device	Slight Film
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		