2004 Hitachi ZX55UR Mini Excavator

Basic information			
Model	ZX55UR	Serial No.	10824
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2004	Working hours	
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Front Attachment	Offset	Type of Shoe	Grouser
Bucket Attachment	Standard	Other	EPA, Air Conditioner
Annogranco			
Appearance	Deformed / Dent	Side Covers	Deformed / Dent
Engine Cover			
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded	Door	Good Condition
Interior			
Cabin Interior	Good Condition	Seat	Dirty
Console	Good Condition	Air Conditioner	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit		Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
	t Wear: Moderate / within Service Lir		
Undercarriage / Chassis /	/ Tiron		
.	Tiles	Wear: Track Link	
Seize: Track Links	No	Stretching (Right)	Moderate
Wear: Track Link	Moderate	Wear: Track Link Tread	Moderate / within Service Limit
Stretching (Left)	Woderate	(Right)	Widderate / Within Gervice Emit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins &	Moderate / within Service Limit	Wear: Track Shoe / Rubber	Moderate / within Service Limit
Bushings (Left)	Moderate / Within Oct VICE LITH	Shoe	Wilderate / Within Oct VICE LITTIL
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Moderate / within Service Limit
Wear: Sprocket (Left)	Moderate / within Service Limit	Oil Leak: Travel Device	Slight Film
Oil Leak: Travel Pipes	Slight Film		Y
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
	Moderate Oozing	Oil Leak: Oil Cooler	None
Oil Leak: Engine		OII LOUN. OII OOOIGI	110110
	························ " ············	Leak: Cooling Pines	None
Oil Leak: Engine Leak: Radiator Oil Leak: Fuel System	None Slight Film	Leak: Cooling Pipes Oil Leak: Upper Structure	None None

Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		