2005 IHI 30VZ Mini Excavator

Basic information			
Model	30VZ	Serial No.	WT001028
Product category	Mini Excavator	Manufacturer	IHI
Year of manufacture	2005	Working hours	
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canopy
Cabin Type	Standard	Front Attachment	Standard
Type of Shoe	Rubber	Bucket Attachment	Standard
Appearance	Defermed / Dent	Cide Covers	Ornakad
Engine Cover	Deformed / Dent	Side Covers	Cracked
Under Covers	Good Condition Good Condition	Counter Weight	Good Condition
Main Frame Cabin	Deformed / Dent	Track Frame	Good Condition
Javill	Detofffied / Defit		
Interior			
Cabin Interior	Damaged	Seat	Torn
Console	Malfunction		
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
	Normal	Arm	Normal
Boom	Normal Moderate / within Service Limit	Arm Wear: Boom / Arm Joint Din	Normal
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin Wear: Other Pins	Moderate / within Service Limit Moderate / within Service Limit
Wear: Arm Tip Pin	Heavy Wear: Moderate / within Service Limit		
		. Wear / Delormation. Diade	Deformation, Woutlate
Undercarriage / Chassis /	Tires		
Wear: Track Link	Slight	Wear: Track Link	Slight
Stretching (Right)		Stretching (Left)	
Wear: Track Link Tread (Right)	Moderate / within Service Limit	Wear: Track Link Tread (Left)	Moderate / within Service Limit
Wear: Track Shoe / Rubber		Broken / Crack: Rubber	
		Droken / Crack, Rubber	
Shoe	Moderate / within Service Limit	Shoe (Right)	Some Tears
		Shoe (Right)	
Broken / Crack: Rubber Shoe (Left)	Some Tears	Shoe (Right) Missing: Rubber Shoe Core	No
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers	Some Tears Moderate / within Service Limit	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers	No Moderate / within Service Limit
Shoe Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers	Some Tears Moderate / within Service Limit None	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers	No Moderate / within Service Limit None
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right)	Some Tears Moderate / within Service Limit None Moderate / within Service Limit	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	No Moderate / within Service Limit None Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Some Tears Moderate / within Service Limit None Moderate / within Service Limit	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	No Moderate / within Service Limit None Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None None	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil Leak: Boom Cylinder	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None Excessive / Required to Repair
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None None Moderate Oozing	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None Excessive / Required to Repair Slight Film
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None None Moderate Oozing None	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None Excessive / Required to Repair Slight Film None
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder Oil Leak: Offset Cylinder Oil Leak: Engine Leak: Radiator	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None None None Moderate Oozing None None	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder Oil Leak: Oil Cooler	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None Excessive / Required to Repair Slight Film None None
Broken / Crack: Rubber Shoe (Left) Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right) Oil Leak: Travel Device	Some Tears Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None None None Moderate Oozing None None None	Shoe (Right) Missing: Rubber Shoe Core Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left) Oil Leak: Travel Pipes Oil Leak: Boom Cylinder Oil Leak: Bucket Cylinder Oil Leak: Blade Cylinder Oil Leak: Oil Cooler Leak: Cooling Pipes	No Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit None Excessive / Required to Repair Slight Film None None None

Overall Rating

Appearance Evaluation Poor Rust / Corrosion Moderate / within Service Limit

Overall Rating Usable