## 2005 Hitachi ZX40U-2 Mini Excavator

Basic information			
Model	ZX40U-2	Serial No.	10528
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2005	Working hours	
Engine No.			
Detail Information			
	Dantal	Cabin / Canany	C
Job Status Front Attachment	Rental Standard	Cabin / Canopy	Canopy Grouser with Pad
Bucket Attachment	Standard	Type of Shoe Other	Piping, EPA, Multi Lever
bucket Attachment	Standard	Ottlei	riping, EPA, iviuiti Levei
Appearance			
Engine Cover	Good Condition	Side Covers	Deformed / Dent
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Torn	Console	Good Condition
Operation			
Operation	Nieman	Fuhavet O O-!	Name
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tires		
<del>.</del>		Wear: Track Link	
Seize: Track Links	No	Stretching (Right)	Moderate
Wear: Track Link	Moderate	Wear: Track Link Tread	Moderate / within Service Limit
Stretching (Left)	moderate	(Right)	Moderate / Within Oct VICE LITTIL
Wear: Track Link Tread	Moderate / within Service Limit	Wear: Track Link Pins &	Moderate / within Service Limit
(Left) Wear: Track Link Pins &		Bushings (Right) Wear: Track Shoe / Rubber	
vvear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Shoe	Slight
Bent / Broken / Missing:			Ol: 14
Track Shoe	more than 10 Pieces	Wear: Rubber Pad	Slight
Broken / Missing: Rubber	No	Missing: Rubber Pad	No
Pad			
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None

Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	Slight Film
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		