## 2007 Others SH120-3 Hydraulic Excavator

Dadic information			
Basic information  Model	SH120-3	Serial No.	120A3-6910
Product category	Hydraulic Excavator	Manufacturer	Others
Year of manufacture	2007	Working hours	Others
Engine No.	2007	vvorking riours	
·····			
Detail Information		0.1: /0	
Job Status	Rental	Cabin / Canopy	Cabin
Cabin Type	Standard Standard	Front Attachment	Standard
Type of Shoe	Grouser with Pad	Bucket Attachment	Standard
Other	Piping, Air Conditioner		
Appearance		12.	
Engine Cover	Good Condition	Side Covers	Good Condition
Under Covers	Deformed / Dent	Counter Weight	Scratched
Main Frame	Good Condition	D Frame	Deformed / Dent
Track Frame	Good Condition	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Reiforcement	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
	Heavy	Wear: Other Pins	Moderate / within Service Limit
Wear: Arm Tip Pin			
	Wear: Moderate / within Service Li	mit	
		mit	
Wear / Deformation: Bucket Undercarriage / Chassis /		mit  Wear: Track Link  Stretching (Right)	Moderate
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link	/ Tires	Wear: Track Link	Moderate  Moderate / within Service Limit
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread	<sup>/</sup> Tires No	Wear: Track Link Stretching (Right) Wear: Track Link Tread	
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left)	/ Tires No Moderate	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins &	Moderate / within Service Limit
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe	No Moderate  Moderate / within Service Limit	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber	Moderate / within Service Limit  Moderate / within Service Limit
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad	No  Moderate  Moderate / within Service Limit  Moderate / within Service Limit  No  No	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers	No No Moderate Moderate / within Service Limit Moderate / within Service Limit No No Moderate / within Service Limit	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace  No  Moderate / within Service Limit
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers	No Moderate Moderate / within Service Limit Moderate / within Service Limit No No Moderate / within Service Limit No	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace  No  Moderate / within Service Limit  None
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right)	No Moderate Moderate / within Service Limit Moderate / within Service Limit No No Moderate / within Service Limit No Moderate / within Service Limit None Moderate / within Service Limit	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace  No  Moderate / within Service Limit  None  Moderate / within Service Limit
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	No Moderate Moderate / within Service Limit Moderate / within Service Limit No No Moderate / within Service Limit Noe Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit
Wear / Deformation: Bucket Undercarriage / Chassis / Seize: Track Links Wear: Track Link Stretching (Left) Wear: Track Link Tread (Left) Wear: Track Link Pins & Bushings (Left) Bent / Broken / Missing: Track Shoe Broken / Missing: Rubber Pad Wear: Upper Rollers Oil Leak: Rollers Wear: Front Idler (Right) Wear: Sprocket (Right)	No Moderate Moderate / within Service Limit Moderate / within Service Limit No No Moderate / within Service Limit No Moderate / within Service Limit None Moderate / within Service Limit	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace  No  Moderate / within Service Limit  None  Moderate / within Service Limit
	No Moderate Moderate / within Service Limit Moderate / within Service Limit No No Moderate / within Service Limit Noe Moderate / within Service Limit None Moderate / within Service Limit Moderate / within Service Limit Moderate / within Service Limit	Wear: Track Link Stretching (Right) Wear: Track Link Tread (Right) Wear: Track Link Pins & Bushings (Right) Wear: Track Shoe / Rubber Shoe Wear: Rubber Pad Missing: Rubber Pad Wear: Lower Rollers Broken / Missing: Rollers Wear: Front Idler (Left) Wear: Sprocket (Left)	Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit  Excessive / Required to replace  No  Moderate / within Service Limit  None  Moderate / within Service Limit  Moderate / within Service Limit  Moderate / within Service Limit

Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None
Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None
Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	None
Oil Leak: Swing Device	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	No
Overall Rating	Fair		