

2001 Hitachi ZX70 Hydraulic Excavator

| Basic information | | | |
|---|---------------------------------------|--|---------------------------------|
| Model | ZX70 | Serial No. | 60382 |
| Product category | Hydraulic Excavator | Manufacturer | Hitachi |
| Year of manufacture | 2001 | Working hours | |
| Engine No. | | | |
| Detail Information | | | |
| Job Status | Rental | Cabin / Canopy | Cabin |
| Cabin Type | Standard | Type of Shoe | Grouser |
| Bucket Attachment | Standard | Other | Piping, EPA, Air Conditioner |
| Appearance | | | |
| Engine Cover | Good Condition | Side Covers | Rusted / Corroded |
| Under Covers | Missing | Counter Weight | Good Condition |
| Main Frame | Good Condition | D Frame | Good Condition |
| Track Frame | Deformed / Dent | Cabin | Rusted / Corroded |
| Door | Good Condition | | |
| Interior | | | |
| Cabin Interior | Good Condition | Seat | Good Condition |
| Console | Good Condition | Air Conditioner | Good |
| Operation | | | |
| Engine | Normal | Exhaust Gas Color | Normal |
| Swing | Normal | Wear: Swing Bearing | Moderate / within Service Limit |
| Traveling | Normal | Front Attachment | Normal |
| Pump Device | Normal | | |
| Front & Pins | | | |
| Boom | Normal | Arm | Deformed / Dent |
| Wear: Boom Foot Pin | Moderate / within Service Limit | Wear: Boom / Arm Joint Pin | Moderate / within Service Limit |
| Wear: Arm Tip Pin | Moderate / within Service Limit | Wear: Other Pins | Moderate / within Service Limit |
| Wear / Deformation: Bucket | Wear: Moderate / within Service Limit | | |
| Undercarriage / Chassis / Tires | | | |
| Seize: Track Links | No | Wear: Track Link Stretching (Right) | Moderate |
| Wear: Track Link Stretching (Left) | Moderate | Wear: Track Link Tread (Right) | Moderate / within Service Limit |
| Wear: Track Link Tread (Left) | Moderate / within Service Limit | Wear: Track Link Pins & Bushings (Right) | Moderate / within Service Limit |
| Wear: Track Link Pins & Bushings (Left) | Moderate / within Service Limit | Wear: Track Shoe / Rubber Shoe | Moderate / within Service Limit |
| Bent / Broken / Missing: Track Shoe | 1 - 4 Pieces | Wear: Upper Rollers | Moderate / within Service Limit |
| Wear: Lower Rollers | Moderate / within Service Limit | Oil Leak: Rollers | None |
| Broken / Missing: Rollers | None | Wear: Front Idler (Right) | Slight |
| Wear: Front Idler (Left) | Slight | Wear: Sprocket (Right) | Slight |
| Wear: Sprocket (Left) | Slight | Oil Leak: Travel Device | None |
| Oil Leak: Travel Pipes | None | | |
| Oil / Water / Air Leakage | | | |
| Oil Leak: Front Pipes | None | Oil Leak: Boom Cylinder (Right) | None |
| Oil Leak: Arm Cylinder (Right) | Moderate Oozing | Oil Leak: Bucket Cylinder (Right) | None |
| Oil Leak: Engine | Slight Film | Oil Leak: Oil Cooler | None |
| Leak: Radiator | None | Leak: Cooling Pipes | None |

| | | | |
|------------------------------|-------------|-------------------------------|---------------------------------|
| Oil Leak: Fuel System | None | Oil Leak: Control Valve | None |
| Oil Leak: Low Pressure Pipes | None | Oil Leak: High Pressure Pipes | Slight Film |
| Oil Leak: Pilot Pipes | None | Oil Leak: Pilot Valve | None |
| Oil Leak: Center Joint | None | Oil Leak: Swing Device | None |
| Oil Leak: Pump Device | Slight Film | | |
| Overall Rating | | | |
| Appearance Evaluation | Fair | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating | Fair | | |