2000 Hitachi ZX75US Hydraulic Excavator

Desir inform			
Basic information	7/75110	Coriol No	20042
Model	ZX75US	Serial No.	30042
Product category Year of manufacture	Hydraulic Excavator 2000	Manufacturer Working hours	Hitachi
Fear of manufacture Engine No.	2000	Working nours	
Detail Information			
Job Status	Forestry	Cabin / Canopy	Cabin
Front Attachment	Standard	Type of Shoe	Grouser
Bucket Attachment	without Bucket	Other	Piping, Air Conditioner, Multi Leve
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	D Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Door	Good Condition		
Interior			
Cabin Interior	Defect / Missing	Seat	Torn
Console	Good Condition	Air Conditioner	Good
<u> </u>			
Operation	NI	Full sured O. O. I	N11
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Repair Mark	Arm	Reinforcement
Wear: Boom Foot Pin	Heavy		Moderate / within Service Limit
Wear / Deformation: Bucket	Good	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis /	Tires		
Seize: Track Links	No	Wear: Track Link	Moderate
Seize. Hack Liliks	INO	Stretching (Right)	Woderate
Wear: Track Link	Moderate	Wear: Track Link Tread	Moderate / within Service Limit
Stretching (Left)		(Right)	
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Excessive / Required to replace
Wear: Track Link Pins & Bushings (Left)	Excessive / Required to replace	Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit
Bent / Broken / Missing: Track Shoe	1 - 4 Pieces	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Excessive / Required to replace	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil / Water / Air Leakage Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Front Pipes		(Right)	
Oil Leak: Front Pipes Oil Leak: Arm Cylinder	None None	_	None
Oil Leak: Front Pipes Oil Leak: Arm Cylinder (Right)		(Right) Oil Leak: Bucket Cylinder	
Oil / Water / Air Leakage Oil Leak: Front Pipes Oil Leak: Arm Cylinder (Right) Oil Leak: Blade Cylinder Oil Leak: Oil Cooler	None	(Right) Oil Leak: Bucket Cylinder (Right)	None

Oil Leak: Control Valve	Slight Film	Oil Leak: Low Pressure Pipes	Slight Film
Oil Leak: High Pressure Pipes	Slight Film	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Center Joint	Slight Film
Oil Leak: Swing Device	Slight Film	Oil Leak: Pump Device	Slight Film
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		