1997 Others FL302-2 Wheel Loader

Basic information			
Model	FL302-2	Serial No.	5029
Product category	Wheel Loader	Manufacturer	Others
Year of manufacture	1997	Working hours	3695 hours
Engine No.			
Detail Information			
Job Status	Rental	Type of Tire	Normal
icense Plate	No	Documents	Unknown
Cabin / Canopy	Canopy	Power Transmission System	HST
Orive System	All Wheel Drive	Size of Tire	12.5/70-16-6PR
Bucket Attachment	Loading BK		
Appearance			
Main Frame	Good Condition	Front Frame	Good Condition
Counter Weight	Good Condition	Cabin	Good Condition
Interior			
Seat	Torn	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
rngme Fraveling	Normal	HST Motor	Normal
Front Attachment	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Side Break	Normal		
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Near: Front Pins &		Wear: Bucket Pins &	
Bushings	Slight	Bushings	Slight
Wear: Center Pins	Slight	Wear: Bucket Side Plate	Slight
Vear: Bucket Lip	Slight	Wear: Bucket Bottom Plate	
Wear: Tooth / Cutting Edges	Slight		
Undercarriage / Chassis /	Tires		
Scratches: Tire (Front-		Wear: Tire (Front-Right	Clight
Right Wheel)	Slight	wheel)	Slight
Scratches: Tire (Front-Left Wheel)	Slight	Wear: Tire (Front-Left Wheel)	Slight
viieei)	Slight	Wear: Tire (Rear-Right Wheel)	Slight
Scratches: Tire (Rear-Left Wheel)	Slight	Wear: Tire (Rear-Left Wheel)	Slight
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	None	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
eak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	None	Oil Leak: Low Pressure	None

Oil Leak: High Pressure Pipes	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		