

2008 Hitachi ZX30UR-2 Mini Excavator

Basic information			
Model	ZX30UR-2	Serial No.	30881
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2008	Working hours	4160 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canopy
Front Attachment	Offset	Type of Shoe	Rubber
Width of Track Shoe	300	Bucket Attachment	Standard
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Rusted / Corroded
Counter Weight	Scratched	Main Frame	Rusted / Corroded
Track Frame	Rusted / Corroded	Cabin	Rusted / Corroded
Interior			
Seat	Good Condition	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Heavy
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Excessive / Required to replace
Broken / Crack: Rubber Shoe (Left)	Some Tears	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	Slight Film	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	Slight Film

Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		