

## 2004 Hitachi ZX30U-2 Mini Excavator

Basic information			
Model	ZX30U-2	Serial No.	10599
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2004	Working hours	4212 hours
Engine No.	09404		
Detail Information			
Job Status	Others	Cabin / Canopy	Canopy
Front Attachment	Standard	Type of Shoe	Rubber
Width of Track Shoe	300	Bucket Attachment	Wide Bucket
Other	EPA		
Appearance			
Engine Cover	Rusted / Corroded	Side Covers	Deformed / Dent
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Torn	Console	Faded
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	Slight
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Good	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis / Tires			
Wear: Track Link Stretching (Right)	Slight	Wear: Track Link Stretching (Left)	Slight
Wear: Track Shoe / Rubber Shoe	Slight	Broken / Crack: Rubber Shoe (Right)	Some Tears
Broken / Crack: Rubber Shoe (Left)	Some Tears	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Repainted	Rust / Corrosion	Moderate / within Service Limit

