2006 Hitachi ZX30UR-2 Mini Excavator

Basic information			
Model	ZX30UR-2	Serial No.	30221
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2006	Working hours	5568 hours
Engine No.			
Detail Information			
Cabin / Canopy	Canopy	Cabin Type	Standard
Front Attachment	Standard	Type of Shoe	Rubber
Width of Track Shoe	300	Bucket Attachment	Standard
Other	EPA	Ducket / Machinion	Claridata
Appearance			
Engine Cover	Deformed / Dent	Side Covers	Good Condition
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition	Tradict raino	2334 Condition
Interior	<u></u>		
Seat	Good Condition	Console	Good Condition
Operation			
	Normal	Exhaust Gas Color	Normal
Engine	Normal		Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins	Marmal	Δ κικο	Normal
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Slight
Wear / Deformation: Bucket		Wear / Deformation: Blade	Normal
Undercarriage / Chassis /	Tires		
Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	No
Broken / Crack: Rubber Shoe (Left)	No	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Slight	Wear: Lower Rollers	Slight
Oil Leak: Rollers	None	Broken / Missing: Rollers	None
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oli Leak. I dei Oystelli		Oil Leak: Pilot Pipes	None
	None		
Oil Leak: Under Carriage Oil Leak: Pilot Valve	None None	Oil Leak: Pump Device	None
Oil Leak: Under Carriage Oil Leak: Pilot Valve			
Oil Leak: Under Carriage			