

# 1998 Komatsu CD60R-1 Carrier

Basic information			
Model	CD60R-1	Serial No.	1550
Product category	Carrier	Manufacturer	Komatsu
Year of manufacture	1998	Working hours	6211 hours
Engine No.			
Detail Information			
Type of Shoe	Grouser	Loading platform type	Gravel carrier
Other	Heater	Main Frame	Rusted / Corroded
Appearance			
Track Frame	Rusted / Corroded	Front bumper	Deformed / Dent, Rusted / Corroded
Cabin / Canopy	Rusted / Corroded	Door	Latch Malfunction
Cabin Interior	Torn		
Interior			
Seat	Torn	Console	Faded, Missing
Wear: Track Link Stretching (Right)	Moderate		
Undercarriage / Chassis / Tires			
Fixation: Track shoe	No	Wear: Rubber Shoe	Moderate / within Service Limit
Wear: Pivot shaft	No	Broken / Missing: Rollers	No
Wear: Front Idler (Right)	Moderate / within Service Limit	Wear: Front Idler (Left)	Moderate / within Service Limit
Wear: Sprocket (Right)	Moderate / within Service Limit	Wear: Sprocket (Left)	Moderate / within Service Limit
Oil Leak: Travel Device	No	Oil Leak: Travel Pipes	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Operation			
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Missing: Rubber Shoe Core	No
Wear: Upper Rollers	Moderate / within Service Limit	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	No		
Oil / Water / Air Leakage			
Oil Leak: High Pressure Pipes	No	Oil Leak: Center Joint	No
Oil Leak: Swing Device	No	Pump Device	No
Oil Leak: Pilot Valve	No	Oil Leak: Pilot Pipes	No
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Dump cylinder (Right)	No
Break	Normal	Dump cylinder (Left)	Slight Film
Side Break	Normal	Oil Leak: Engine	No
Dumping	Normal		
?? ? ??			
Vessel	Deformation: Moderate, Cracked	Frame	Deformation: Moderate
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Heavy
Overall Rating	Fair		