

## 2001 Kubota U-35-3 Mini Excavator

Basic information			
Model	U-35-3	Serial No.	30009
Product category	Mini Excavator	Manufacturer	Kubota
Year of manufacture	2001	Working hours	974 hours
Engine No.	7CW0489		
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canopy
Front Attachment	Standard	Type of Shoe	Rubber
Width of Track Shoe	300	Bucket Attachment	Standard
Appearance			
Engine Cover	Cracked	Side Covers	Cracked
Under Covers	Good Condition	Counter Weight	Scratched
Main Frame	Good Condition	Track Frame	Good Condition
Cabin	Rusted / Corroded		
Interior			
Seat	Dirty	Console	Faded
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Moderate / within Service Limit
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Reinforcement
Wear: Boom Foot Pin	Moderate / within Service Limit	Wear: Boom / Arm Joint Pin	Moderate / within Service Limit
Wear: Arm Tip Pin	Moderate / within Service Limit	Wear: Other Pins	Moderate / within Service Limit
Wear / Deformation: Bucket	Wear: Moderate / within Service Limit	Wear / Deformation: Blade	Wear: Moderate / within Service Limit
Undercarriage / Chassis / Tires			
Wear: Track Link Stretching (Right)	Slight	Wear: Track Link Stretching (Left)	Slight
Wear: Track Link Tread (Right)	Moderate / within Service Limit	Wear: Track Link Tread (Left)	Moderate / within Service Limit
Wear: Track Shoe / Rubber Shoe	Moderate / within Service Limit	Broken / Crack: Rubber Shoe (Right)	Some Tears
Broken / Crack: Rubber Shoe (Left)	Some Tears	Wear: Upper Rollers	Moderate / within Service Limit
Wear: Lower Rollers	Moderate / within Service Limit	Oil Leak: Rollers	1 - 4 Pieces
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Moderate / within Service Limit
Wear: Front Idler (Left)	Moderate / within Service Limit	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	Slight Film		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	Slight Film	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	Moderate Oozing
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	Slight Film	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit

