

## 2006 Kubota RX-503S Mini Excavator

Basic information			
Model	RX-503S	Serial No.	30613
Product category	Mini Excavator	Manufacturer	Kubota
Year of manufacture	2006	Working hours	5470 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canopy
Front Attachment	Offset	Type of Shoe	Grouser with Pad
Width of Track Shoe	400	Bucket Attachment	Standard
Other	Multi Lever		
Appearance			
Engine Cover	Good Condition	Side Covers	Rusted / Corroded
Under Covers	Rusted / Corroded	Counter Weight	Scratched
Main Frame	Rusted / Corroded	Track Frame	Rusted / Corroded
Cabin	Rusted / Corroded		
Interior			
Seat	Torn	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Deformed / Dent
Wear: Boom Foot Pin	Heavy	Wear: Boom / Arm Joint Pin	Heavy
Wear: Arm Tip Pin	Heavy	Wear: Other Pins	Heavy
Wear / Deformation: Bucket	Deformation: Moderate	Wear / Deformation: Blade	Deformation: Moderate
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Moderate / within Service Limit
Wear: Track Link Tread (Left)	Moderate / within Service Limit	Wear: Track Link Pins & Bushings (Right)	Moderate / within Service Limit
Wear: Track Link Pins & Bushings (Left)	Moderate / within Service Limit	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Rubber Pad	Moderate / within Service Limit
Broken / Missing: Rubber Pad	Broken / Missing (Left)	Missing: Rubber Pad	More than 10 Pieces
Wear: Upper Rollers	Excessive / Required to replace	Wear: Lower Rollers	Moderate / within Service Limit
Oil Leak: Rollers	None	Broken / Missing: Rollers	1 - 4 Pieces
Wear: Front Idler (Right)	Slight	Wear: Front Idler (Left)	Slight
Wear: Sprocket (Right)	Slight	Wear: Sprocket (Left)	Slight
Oil Leak: Travel Device	None	Oil Leak: Travel Pipes	None
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Offset Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None

Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None
Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		