1900 Others MG230 Motor Grader

Basic information			
Model	MG230	Serial No.	2GA00862
Product category	Motor Grader	Manufacturer	Others
Year of manufacture	1900	Working hours	1216 hours
Engine No.			
Detail Information			
Power Transmission	Torque Converter	Size of Tire (Rear)	11.00-20-12PR
System License Number Plate	No	,	
	140		
Appearance			
Front Frame	Rusted / Corroded	Main Frame	Rusted / Corroded
Blade frame	Rusted / Corroded	Front tie rod	Good Condition
Cabin / Canopy	Rusted / Corroded		
Interior	-		NA 16 - c'
Seat	Torn	Console	Malfunction
Operation			
Wear: Tire (Front-Right wheel)	Moderate / within Service Limit	Wear: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Front- Right Wheel)	Moderate / within Service Limit	Wear: Tire (Rear-Right Wheel)	Moderate / within Service Limit
Wear: Tire (Rear-Left Wheel)	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No	Oil Leak: Differential Gear Case	No
Tandem case	No	Air pipes	No
Front & Pins			
Scratches: Tire (Rear-Right Wheel)	Moderate / within Service Limit	Scratches: Tire (Front-Left Wheel)	Moderate / within Service Limit
Scratches: Tire (Rear-Left Wheel)	Moderate / within Service Limit		
Oil / Water / Air Leakage			
Scurryfire cylinder	No	Steering Cylinder (Right)	Slight Film
Steering Cylinder (Left)	Slight Film	Front tire tilt cylinder	Slight Film
Articulated cylinder	No	Blade frame tilt cylinder (Right)	No
Blade frame tilt cylinder (Left)	No	Blade frame turning motor	No
Blade slide cylinder	No	Oil Leak: Engine	No
Steering pump	No	Transmission / Torque Converter	Slight Film
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Steering	Normal	Break	Normal
Side Break	Normal	Front Attachment	Normal
Articulated	Normal	Hydraulic pump	Normal
Wear: Center Pins Scurryfire	Moderate / within Service Limit Missing craw	Wear / Deformation: Blade	Wear: Moderate / within Service Limi
Undercarriage / Chassis /	Tires		
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No

Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	No	Oil Leak: Pilot Pipes	No
Pump Device	Slight Film		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		