

1989 TCM 820-2 Wheel Loader

Basic information			
Model	820-2	Serial No.	63305428
Product category	Wheel Loader	Manufacturer	TCM
Year of manufacture	1989	Working hours	1928 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Type of Tire	Normal
Cabin / Canopy	Canopy	Cabin Type	Standard
Power Transmission System	Torque Converter	Drive System	All Wheel Drive
Size of Tire	17.5/65-20-10PR	Bucket Attachment	Loading BK
Appearance			
Main Frame	Good Condition	Front Frame	Good Condition
Counter Weight	Good Condition	Cabin	Good Condition
Interior			
Seat	Torn	Console	Malfunction
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	Pump Device	Normal
Steering	Normal	Break	Normal
Side Break	Normal		
Front & Pins			
Lift(Push)Arm	Normal	Bellcrank	Normal
Wear: Front Pins & Bushings	Moderate / within Service Limit	Wear: Bucket Pins & Bushings	Moderate / within Service Limit
Wear: Center Pins	Moderate / within Service Limit	Wear: Bucket Side Plate	Excessive / Required to replace
Wear: Bucket Lip	Slight	Wear: Bucket Bottom Plate	Excessive / Required to replace
Wear: Tooth / Cutting Edges	Slight		
Undercarriage / Chassis / Tires			
Scratches: Tire (Front-Right Wheel)	Slight	Wear: Tire (Front-Right wheel)	Slight
Scratches: Tire (Front-Left Wheel)	Slight	Wear: Tire (Front-Left Wheel)	Slight
Scratches: Tire (Rear-Right Wheel)	Slight	Wear: Tire (Rear-Right Wheel)	Slight
Scratches: Tire (Rear-Left Wheel)	Slight	Wear: Tire (Rear-Left Wheel)	Slight
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Lift Cylinder (Right)	None
Oil Leak: Lift Cylinder (Left)	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Steering Cylinder	Moderate Oozing	Oil Leak: Engine	None
Oil Leak: Oil Cooler	None	Leak: Radiator	None
Leak: Cooling Pipes	None	Oil Leak: Fuel System	None
Oil Leak: Control Valve	None	Oil Leak: Low Pressure Pipes	None

Oil Leak: High Pressure Pipes	None	Oil Leak: Pump Device	None
Oil Leak: Transmission / Torcon	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		