

2006 Hitachi ZX35U-2 Mini Excavator

Basic information			
Model	ZX35U-2	Serial No.	10839
Product category	Mini Excavator	Manufacturer	Hitachi
Year of manufacture	2006	Working hours	4012 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Canopy
Front Attachment	Standard	Type of Shoe	Grouser
Width of Track Shoe	300	Bucket Attachment	Standard
Other	Piping, EPA, Multi Lever, Arm Crane		
Appearance			
Engine Cover	Good Condition	Side Covers	Good Condition
Under Covers	Good Condition	Counter Weight	Good Condition
Main Frame	Good Condition	Track Frame	Good Condition
Cabin	Good Condition		
Interior			
Seat	Torn	Console	Good Condition
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	Slight
Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear / Deformation: Bucket	Good	Wear / Deformation: Blade	Normal
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Moderate
Wear: Track Link Stretching (Left)	Moderate	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Slight
Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder	None
Oil Leak: Arm Cylinder	None	Oil Leak: Bucket Cylinder	None
Oil Leak: Swing Cylinder	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Upper Structure	None
Oil Leak: Under Carriage	None	Oil Leak: Pilot Pipes	None

Oil Leak: Pilot Valve	None	Oil Leak: Pump Device	None
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		