

1900 Komatsu FD30H-11 Forklift

Basic information			
Model	FD30H-11	Serial No.	471844
Product category	Forklift	Manufacturer	Komatsu
Year of manufacture	1900	Working hours	2145 hours
Engine No.			
Detail Information			
Power Transmission System	Direct Drive	Drive System	Front Drive
Size of Tire (Front)	28x9-15-7.00-SOLID	Size of Tire (Rear)	6.50-10-5.00-SOLID
Rear wheel tire	2	Max working height	4
Fuel System	Diesel	Documents	Unknown
License Number Plate	No		
Appearance			
Main Frame	Good Condition	Mast	Good Condition
Fin guard	Deformed / Dent	Engine Cover	Good Condition
Lever	Good Condition	Cabin / Canopy	Good Condition
Interior			
Seat	Torn	Console	Faded
Operation			
Scratches: Tire	Moderate / within Service Limit	Wear: Tire	Excessive / Required to replace
Oil Leak: Axle	No	Oil Leak: Differential Gear Case	No
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Undercarriage / Chassis / Tires			
Lift cylinder (Right)	No	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Pump Device	No		
Oil / Water / Air Leakage			
Lift cylinder (Left)	No	Oil Leak: Tilt Cylinder (Right)	No
Oil Leak: Tilt Cylinder (Left)	No	Oil Leak: Steering Cylinder	Slight Film
Oil Leak: Engine	Slight Film	Transmission / Torque Converter	No
Engine	Normal	Exhaust Gas Color	Normal
Traveling	Normal	Transmission / Torque Converter	Normal
Clutch	Normal	Steering	Normal
Break	Normal	Side Break	Normal
Wear: Fork	Slight		
Front & Pins			
Leak: Cooling Pipes	No	Oil Leak: Fuel System	No
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		