

1900 Sumitomo HN200WHK Roller

Basic information			
Model	HN200WHK	Serial No.	N20F0-0002
Product category	Roller	Manufacturer	Sumitomo
Year of manufacture	1900	Working hours	4176 hours
Engine No.			
Detail Information			
Power Transmission System	HST	Drive System	Rear Drive
Appearance			
Main Frame	Rusted / Corroded	Canopy	Rusted / Corroded
Interior			
Seat	Good Condition	Console	Faded
Operation			
Wear / Scratches: Tire (Front Wheel)	Moderate / within Service Limit	Wear / Scratches: Tire (Rear Wheel)	Moderate / within Service Limit
Wear / Broken: brush (Front wheel)	Moderate / within Service Limit	Wear / Broken: brush (Rear wheel)	Moderate / within Service Limit
Oil Leak: Travel Device	No	Oil Leak: Travel Pipes	No
Oil / Water / Air Leakage			
Oil Leak: Steering Cylinder	Slight Film	Oil Leak: Engine	Slight Film
Pump Device	Slight Film	Engine	Normal
Exhaust Gas Color	Normal	Traveling	Normal
Break	Normal	Side Break	Normal
Undercarriage / Chassis / Tires			
Oil Leak: Oil Cooler	No	Leak: Radiator	No
Leak: Cooling Pipes	No	Oil Leak: Fuel System	Slight Film
Oil Leak: Control Valve	No	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	No		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Fair		