

# 1996 Others NF36W Asphalt Paver

Basic information			
Model	NF36W	Serial No.	NF36W0007
Product category	Asphalt Paver	Manufacturer	Others
Year of manufacture	1996	Working hours	6456 hours
Engine No.			
Detail Information			
Underbody	Tire		
Appearance			
Tractor unit	Rusted / Corroded	Screed	Rusted / Corroded
Extension screed	Rusted / Corroded	Screed arm	Rusted / Corroded
Screed blade	Rusted / Corroded	Feeder bar	Rusted / Corroded
Hopper	Rusted / Corroded	Tanpaiba	Rusted / Corroded
Screw	Rusted / Corroded	Extension screw	Rusted / Corroded
Push roller	Rusted / Corroded	Main Frame	Rusted / Corroded
Interior			
Console	Faded, Malfunction		
Front & Pins			
Scratches: Tire	Moderate / within Service Limit		
Operation			
Wear: Tire	Moderate / within Service Limit	Oil Leak: Travel Device	No
Oil Leak: Travel Pipes	No		
Undercarriage / Chassis / Tires			
Hopper cylinder (Right)	Slight Film	Hopper cylinder (Left)	Slight Film
Screed support cylinder	No	Extension screed cylinder	No
Cylinder operated pump	Slight Film	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No
Oil Leak: Fuel System	Slight Film	Oil Leak: Control Valve	No
Oil Leak: Low Pressure Pipes	No	Oil Leak: High Pressure Pipes	No
Pump Device	No		
Oil / Water / Air Leakage			
Screed arm cylinder	No	Oil Leak: Engine	Slight Film
Leveling cylinder	No	Engine	Normal
Exhaust Gas Color	White Smoke	Traveling	Normal
Steering	Normal	Break	Normal
Side Break	Normal	Screw	Normal
Hopper condition	Normal	Tamper bar	Normal
Vibration motor	Normal	Screed plate	Normal
Feeder	Normal		
Overall Rating			
Appearance Evaluation	Poor	Rust / Corrosion	Moderate / within Service Limit
Overall Rating	Usable		