

2006 Komatsu PC78US-6N0 Hydraulic Excavator

Basic information			
Model	PC78US-6N0	Serial No.	9845
Product category	Hydraulic Excavator	Manufacturer	Komatsu
Year of manufacture	2006	Working hours	3729 hours
Engine No.			
Detail Information			
Job Status	Civil Engineering	Cabin / Canopy	Cabin
Front Attachment	Standard	Type of Shoe	Grouser
Width of Track Shoe	450	Bucket Attachment	Standard
Other	Piping, EPA, Air Conditioner, Multi Lever, Quick Hitch		
Appearance			
Engine Cover	Good Condition	Side Covers	Deformed / Dent
Under Covers	Good Condition	Counter Weight	Scratched
Main Frame	Good Condition	D Frame	Good Condition
Track Frame	Good Condition	Cabin	Good Condition
Door	Good Condition		
Interior			
Cabin Interior	Good Condition	Seat	Good Condition
Console	Good Condition	Air Conditioner	Good
Operation			
Engine	Normal	Exhaust Gas Color	Normal
Swing	Normal	Wear: Swing Bearing	Slight
Traveling	Normal	Front Attachment	Normal
Pump Device	Normal		
Front & Pins			
Boom	Normal	Arm	Normal
Wear: Boom Foot Pin	Slight	Wear: Boom / Arm Joint Pin	Slight
Wear: Arm Tip Pin	Slight	Wear: Other Pins	Slight
Wear / Deformation: Bucket	Good	Wear / Deformation: Blade	Normal
Undercarriage / Chassis / Tires			
Seize: Track Links	No	Wear: Track Link Stretching (Right)	Slight
Wear: Track Link Stretching (Left)	Slight	Wear: Track Link Tread (Right)	Slight
Wear: Track Link Tread (Left)	Slight	Wear: Track Link Pins & Bushings (Right)	Slight
Wear: Track Link Pins & Bushings (Left)	Slight	Wear: Track Shoe / Rubber Shoe	Slight
Bent / Broken / Missing: Track Shoe	No	Wear: Upper Rollers	Slight
Wear: Lower Rollers	Slight	Oil Leak: Rollers	None
Broken / Missing: Rollers	None	Wear: Front Idler (Right)	Slight
Wear: Front Idler (Left)	Slight	Wear: Sprocket (Right)	Slight
Wear: Sprocket (Left)	Slight	Oil Leak: Travel Device	None
Oil Leak: Travel Pipes	None		
Oil / Water / Air Leakage			
Oil Leak: Front Pipes	None	Oil Leak: Boom Cylinder (Right)	None
Oil Leak: Boom Cylinder (Left)	None	Oil Leak: Arm Cylinder (Right)	None

Oil Leak: Bucket Cylinder (Right)	None	Oil Leak: Blade Cylinder	None
Oil Leak: Engine	None	Oil Leak: Oil Cooler	None
Leak: Radiator	None	Leak: Cooling Pipes	None
Oil Leak: Fuel System	None	Oil Leak: Control Valve	None
Oil Leak: Low Pressure Pipes	None	Oil Leak: High Pressure Pipes	None
Oil Leak: Pilot Pipes	None	Oil Leak: Pilot Valve	None
Oil Leak: Center Joint	None	Oil Leak: Swing Device	None
Oil Leak: Pump Device	None		
Overall Rating			
Appearance Evaluation	Fair	Rust / Corrosion	Slight
Overall Rating	Fair		