

# 1900 TCM 543 Wheel Loader

| Basic information                   |                                 |                                  |                                 |
|-------------------------------------|---------------------------------|----------------------------------|---------------------------------|
| Model                               | 543                             | Serial No.                       | 82416438                        |
| Product category                    | Wheel Loader                    | Manufacturer                     | TCM                             |
| Year of manufacture                 | 1900                            | Working hours                    | 1206 hours                      |
| Engine No.                          |                                 |                                  |                                 |
| Detail Information                  |                                 |                                  |                                 |
| Job Status                          | Others                          | Type of Tire                     | Normal                          |
| License Plate                       | No                              | Cabin / Canopy                   | Canopy                          |
| Power Transmission System           | HST                             | Drive System                     | All Wheel Drive                 |
| Size of Tire                        | 27X8.50-15-4PR                  | Bucket Attachment                | Loading BK                      |
| Appearance                          |                                 |                                  |                                 |
| Main Frame                          | Rusted / Corroded               | Front Frame                      | Rusted / Corroded               |
| Counter Weight                      | Scratched                       | Cabin                            | Rusted / Corroded               |
| Interior                            |                                 |                                  |                                 |
| Seat                                | Torn                            |                                  |                                 |
| Operation                           |                                 |                                  |                                 |
| Engine                              | Normal                          | Exhaust Gas Color                | Normal                          |
| Traveling                           | Normal                          | HST Motor                        | Normal                          |
| Front Attachment                    | Normal                          | Pump Device                      | Normal                          |
| Steering                            | Normal                          | Break                            | Normal                          |
| Side Break                          | Malfunction                     |                                  |                                 |
| Front & Pins                        |                                 |                                  |                                 |
| Lift(Push)Arm                       | Normal                          | Wear: Front Pins & Bushings      | Moderate / within Service Limit |
| Wear: Bucket Pins & Bushings        | Moderate / within Service Limit | Wear: Bucket Side Plate          | Slight                          |
| Wear: Bucket Lip                    | Slight                          | Wear: Bucket Bottom Plate        | Slight                          |
| Wear: Tooth / Cutting Edges         | Slight                          |                                  |                                 |
| Undercarriage / Chassis / Tires     |                                 |                                  |                                 |
| Scratches: Tire (Front-Right Wheel) | Slight                          | Wear: Tire (Front-Right wheel)   | Slight                          |
| Scratches: Tire (Front-Left Wheel)  | Slight                          | Wear: Tire (Front-Left Wheel)    | Slight                          |
| Scratches: Tire (Rear-Right Wheel)  | Slight                          | Wear: Tire (Rear-Right Wheel)    | Excessive / Required to replace |
| Scratches: Tire (Rear-Left Wheel)   | Slight                          | Wear: Tire (Rear-Left Wheel)     | Excessive / Required to replace |
| Oil Leak: Axle                      | No                              | Oil Leak: Differential Gear Case | No                              |
| Oil / Water / Air Leakage           |                                 |                                  |                                 |
| Oil Leak: Front Pipes               | None                            | Oil Leak: Lift Cylinder (Right)  | None                            |
| Oil Leak: Lift Cylinder (Left)      | None                            | Oil Leak: Bucket Cylinder        | Slight Film                     |
| Oil Leak: Engine                    | Slight Film                     | Oil Leak: Oil Cooler             | None                            |
| Leak: Radiator                      | None                            | Leak: Cooling Pipes              | None                            |
| Oil Leak: Fuel System               | None                            | Oil Leak: Control Valve          | None                            |
| Oil Leak: Low Pressure Pipes        | None                            | Oil Leak: High Pressure Pipes    | None                            |
| Oil Leak: Pilot Pipes               | None                            | Oil Leak: Pilot Valve            | None                            |

|                       |        |                  |                                 |
|-----------------------|--------|------------------|---------------------------------|
| Oil Leak: Pump Device | None   |                  |                                 |
| Overall Rating        |        |                  |                                 |
| Appearance Evaluation | Poor   | Rust / Corrosion | Moderate / within Service Limit |
| Overall Rating        | Usable |                  |                                 |